



report date: 2024-03-28

General information

Make	FORD
Model	FOCUS C-MAX ZETEC
Colour	Silver
Year of manufacture	-
Top speed	120 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	165 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-28
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #17	2022-10-06 15:05
MOT test number	803278410162
Result	✓ Passed
Next expiry date	2023-10-05
Advice	Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #16	2022-10-05 10:20
MOT test number	460556907970
Result	✗ Failed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
MAJOR	Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
MAJOR	Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
MAJOR	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #15	2021-10-05 12:37
MOT test number	456785912711
Result	✓ Passed
MOT #14	2019-07-10 11:25
MOT test number	885318798584
Result	✓ Passed

**MOT #13** 2018-07-18 07:47**MOT test number** 502945754795**Result** ✓ Passed**MOT #12** 2018-07-17 13:13**MOT test number** 303452250507**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**DANGEROUS** Nearside Front Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2017-07-17 11:23**MOT test number** 451439819222**Result** ✓ Passed**MOT #10** 2016-05-23 14:17**MOT test number** 275989085986**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #9** 2016-05-23 14:17**MOT test number** 544106414100**Result** ✗ Failed**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #8** 2015-07-13 16:29**MOT test number** 357624695135**Result** ✓ Passed**MOT #7** 2015-07-13 16:29**MOT test number** 808914095116**Result** ✗ Failed**Pass with rectification** Offside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**MOT #6** 2014-03-10 16:11**MOT test number** 896389964011**Result** ✓ Passed**MOT #5** 2014-03-10 08:59**MOT test number** 695069764060**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #4** 2013-03-13 11:48**MOT test number** 706922073026**Result** ✓ Passed**MOT #3** 2012-03-15 10:36**MOT test number** 375145772029**Result** ✓ Passed**MOT #2** 2011-03-16 09:57**MOT test number** 995125871069**Result** ✓ Passed



MOT #1	2010-03-16 11:57
MOT test number	802115570009
Result	✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-03-16
Last registration	2022-10-06
Complete history	See info



Registration #1	2007-03-16	7 mi
Registration #2	2010-03-16	16.118 mi
Registration #3	2011-03-16	20.118 mi
Registration #4	2012-03-15	22.227 mi
Registration #5	2013-03-13	32.980 mi
Registration #6	2014-03-10	43.230 mi
Registration #7	2014-03-10	43.230 mi
Registration #8	2015-07-13	59.635 mi
Registration #9	2016-05-23	68.523 mi
Registration #10	2016-05-23	68.523 mi
Registration #11	2016-05-23	68.523 mi
Registration #12	2016-05-23	68.523 mi
Registration #13	2016-05-23	68.523 mi
Registration #14	2016-05-23	68.523 mi
Registration #15	2016-05-23	68.523 mi
Registration #16	2016-05-23	68.523 mi
Registration #17	2016-05-23	68.523 mi
Registration #18	2016-05-23	68.523 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1783 mm
Height	1558 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1409 kg
Max. allowed weight	1910 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	6Y15639