



report date: 2024-03-28

## General information

Make	VOLVO
Model	V50 D DRIVE SE LUX
Colour	Grey
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 2


Date	2021-07-10
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-07-09
Pictures	30
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-08-31
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	27
Total items failed	3

MOT #18	2023-09-01 16:37
MOT test number	940018568182
Result	✓ Passed
Next expiry date	2024-08-31

MOT #17	2023-08-29 11:49
MOT test number	100813153341
Result	✗ Failed

**DANGEROUS** Offside Rear Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Nearside Rear Inner Sidewall damage run flat

**MAJOR** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #16	2022-08-08 11:26
MOT test number	340137835767
Result	✓ Passed

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge & wearing unevenly (5.2.3 (e))

**MOT #15** 2021-08-14 11:08**MOT test number** 220960714810**Result** ✓ Passed**MOT #14** 2021-08-10 11:59**MOT test number** 473279736059**Result** ✗ Failed**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**MOT #13** 2021-02-26 15:03**MOT test number** 737118378298**Result** ✓ Passed**Advice** Undershields fitted restricting the underside inspection of the vehicle.**MOT #12** 2021-02-26 11:24**MOT test number** 799931576457**Result** ✗ Failed**Advice** Undershields fitted restricting the underside inspection of the vehicle.**DANGEROUS** Nearside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Offside Front Road wheel fixing missing (5.2.1 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))**MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**DANGEROUS** Nearside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**DANGEROUS** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #11**

2020-02-28 10:37

**MOT test number**

691879857451

**Result**

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Under shields fitted prevents inspection to underside of vehicle
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2020-02-28 10:37

**MOT test number**

372687213179

**Result**

✗ Failed

- Advice** Under shields fitted prevents inspection to underside of vehicle
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9**

2019-02-28 15:53

**MOT test number**

485330423095

**Result**

✓ Passed

**MOT #8**

2018-02-14 15:43

**MOT test number**

411909792064

**Result**

✓ Passed

**MOT #7** 2017-02-09 17:11**MOT test number** 720693136647**Result** ✓ Passed**MOT #6** 2017-02-09 17:11**MOT test number** 663437282661**Result** ✗ Failed**Pass with rectification** Nearside Rear position lamp(s) not working (1.1.A.3b)**MOT #5** 2016-02-08 12:52**MOT test number** 356966036684**Result** ✓ Passed**Advice** Front tyres wearing on inner edges**MOT #4** 2015-02-05 09:36**MOT test number** 975036535087**Result** ✓ Passed**MOT #3** 2015-02-05 09:36**MOT test number** 138186535097**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #2** 2014-02-12 14:18**MOT test number** 806803444005**Result** ✓ Passed**MOT #1** 2013-02-21 17:50**MOT test number** 537062453007**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
31 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	31 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>LA10WAO</b>
Plate since	2024-03-28
Current registration	<b>LA10WAO</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-04-22
Last registration	2023-09-01
Complete history	<a href="#">See info</a>



Registration #1	2010-04-22	29 mi
Registration #2	2013-02-21	30.390 mi
Registration #3	2014-02-12	38.911 mi
Registration #4	2015-02-05	47.564 mi
Registration #5	2016-02-08	59.905 mi
Registration #6	2017-02-09	72.205 mi
Registration #7	2017-02-09	72.205 mi
Registration #8	2018-02-14	83.540 mi
Registration #9	2019-02-28	95.887 mi
Registration #10	2020-02-28	103.111 mi
Registration #11	2020-02-28	103.111 mi
Registration #12	2020-02-28	103.111 mi
Registration #13	2020-02-28	103.111 mi
Registration #14	2020-02-28	103.111 mi
Registration #15	2020-02-28	103.111 mi
Registration #16	2020-02-28	103.111 mi
Registration #17	2020-02-28	103.111 mi
Registration #18	2020-02-28	103.111 mi
Registration #19	2020-02-28	103.111 mi
Registration #20	2020-02-28	103.111 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1260602