



RENAULT

EXIOLXA

report date: 2024-03-28

General information

Make	RENAULT
Model	KANGOO SL19 DCI 70
Colour	White
Year of manufacture	2010
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-06-10
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-03-21
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	38
Total items failed	19

MOT #17	2023-03-22 14:28
---------	------------------

MOT test number	816185339059
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-03-21
------------------	------------

- Advice

Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor

Nearside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice

Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor

Offside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))



MOT #16

2023-03-15 14:42

MOT test number

185060385859

Result

✗ Failed

- Minor

Nearside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail

Windscreen washer not working (3.5 (a))
- Fail

Offside Rear Direction indicator adversely affected by the operation of another lamp (4.4.3 (b))
- Advice

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail

Offside Windscreen wiper not working (3.4 (a))
- Minor

Offside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail

Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail

Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice

Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #15**

2022-01-10 16:35

MOT test number

475667769629

Result

✓ Passed

- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14

2020-12-24 15:57

MOT test number

123159110315

Result

✓ Passed

MOT #13

2020-01-16 09:15

MOT test number

762863241696

Result

✓ Passed

MOT #12

2020-01-16 09:15

MOT test number

844284424158

Result

✗ Failed

- Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #11**

2018-12-29 11:54

MOT test number

438267075813

Result

✓ Passed

Advice Offside Rear incorrect coil spring fitted**Advice** Front bonnet pull missing**Minor** Nearside Rear Stop lamp(s) lens defective which has no effect on emitted light cracked lens (4.3.1 (b) (i))**MOT #10**

2018-12-29 08:46

MOT test number

343524044616

Result

✗ Failed

Fail Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Rear Stop lamp(s) lens defective which has no effect on emitted light cracked lens (4.3.1 (b) (i))**Advice** Front bonnet pull missing**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Rear incorrect coil spring fitted**MOT #9**

2017-12-30 12:29

MOT test number

819963387859

Result

✓ Passed

Advice BONNET RELEASE LEVER AND BONNET STAY MISSING**Advice** Offside Front DRIVERS FOOTWELL CARPET IMPEEDS ON THROTTLE PEDAL**Advice** Nearside Front N/S FRONT INNER WHEEL ARCH MISSING

**MOT #8** 2017-12-28 14:51**MOT test number** 989980138988**Result** ✗ Failed**Fail** Front Tyre has ply or cords exposed BOTH FRONT TYRES HAVE CHORDS EXPOSED ON INNER EDGE (4.1.D.1b)**Advice** Nearside Front N/S FRONT INNER WHEEL ARCH MISSING**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Rear Stop lamp not working ALL STOP LIGHTS NOT WORKING (1.2.1b)**Advice** BONNET RELEASE LEVER AND BONNET STAY MISSING**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)**Advice** Offside Front DRIVERS FOOTWELL CARPET IMPEEDS ON THROTTLE PEDAL**MOT #7** 2017-01-05 17:00**MOT test number** 303539030149**Result** ✓ Passed**Advice** Offside Track rod end ball joint has slight play (2.2.B.1f)**MOT #6** 2016-12-17 12:24**MOT test number** 620864165796**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #5** 2015-08-08 09:44**MOT test number** 168110225244**Result** ✓ Passed

**MOT #4** 2014-09-02 14:09**MOT test number** 949365944243**Result** ✓ Passed**MOT #3** 2014-09-02 14:09**MOT test number** 298195244228**Result** ✗ Failed**Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Pass with rectification** Centre Stop lamp not working (1.2.1b)**MOT #2** 2013-03-14 11:34**MOT test number** 819783273015**Result** ✓ Passed**MOT #1** 2013-03-14 09:46**MOT test number** 759163773020**Result** ✗ Failed**Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)



Tax & MOT check

✓
Taxed

Tax due:
1 May 2024

✗
MOT

Expired:
21 March 2024

Tax status	Valid until 1 May
Days left	2
MOT expiry date	21 March 2024
Full MOT history	See MOT history



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	EX10LXA
Plate since	2019-09-29
Current registration	EX10LXA
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-03-18
Last registration	2023-03-22
Complete history	See info



Registration #1	2010-03-18	7 mi
Registration #2	2013-03-14	31.546 mi
Registration #3	2013-03-14	31.546 mi
Registration #4	2014-09-02	49.084 mi
Registration #5	2015-08-08	61.369 mi
Registration #6	2016-12-17	78.645 mi
Registration #7	2017-01-05	79.324 mi
Registration #8	2017-12-28	92.827 mi
Registration #9	2017-12-30	92.827 mi
Registration #10	2019-03-22	92.827 mi
Registration #11	2019-03-22	92.827 mi
Registration #12	2019-03-22	92.827 mi
Registration #13	2019-03-22	92.827 mi
Registration #14	2019-03-22	92.827 mi
Registration #15	2019-03-22	92.827 mi
Registration #16	2019-03-22	92.827 mi
Registration #17	2019-03-22	92.827 mi
Registration #18	2019-03-22	92.827 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	2133 mm
Height	1844 mm
Length	4213 mm

Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	D082219