



report date: 2024-03-29

General information

Make	VOLVO
Model	XC60 D5 SE LUX NAV AWD
Colour	Grey
Year of manufacture	2016
Top speed	130 mph
0 - 60 mph	7.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	212 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	57.7 mpg
Consumption combined	53.3 mpg
CO2 emission	137 g/km
CO2 label	E





report date: 2024-03-29

Entry 1

Listing price [View report](#)



CarCheck.co.uk



MOT history

MOT expiry date	2025-05-02
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	35
Total items failed	6

MOT #9	2024-04-05 13:40
MOT test number	419440678241
Result	✓ Passed
Next expiry date	2025-05-02
Advice	Front Brake pad(s) wearing thin 3mm (1.1.13 (a) (ii))
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #8** 2024-04-05 12:01**MOT test number** 854486932658**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin 3mm (1.1.13 (a) (ii))**Fail** Rear Suspension arm pin or bush excessively worn trailing arm bushes. (5.3.4 (a) (i))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2023-05-03 15:00**MOT test number** 727609410493**Result** ✓ Passed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**Advice** Power steering pipe/hose has slight seepage (2.1.5 (a))

**MOT #6**

2023-05-03 14:15

MOT test number

543798051910

Result**✗ Failed**

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
- Advice** Power steering pipe/hose has slight seepage (2.1.5 (a))
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #5

2022-05-17 11:32

MOT test number

287911624710

Result**✓ Passed**

- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bushes. (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bushes. (5.3.4 (a) (i))

**MOT #4** 2022-05-17 09:34**MOT test number** 674951738527**Result** ✗ Failed

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bushes. (5.3.4 (a) (i))

Advice Offside Rear Tyre slightly damaged stepped (5.2.3 (d) (ii))

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bushes. (5.3.4 (a) (i))

MOT #3 2021-06-04 08:17**MOT test number** 363730464444**Result** ✓ Passed**MOT #2** 2020-10-28 11:11**MOT test number** 595336436068**Result** ✓ Passed

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Rear Brake pad(s) wearing thin 2-2.5mm (1.1.13 (a) (ii))

Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #1 2019-10-19 09:45**MOT test number** 969655564236**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
2 May 2025

Tax status	Valid until 1 December
Days left	215
MOT expiry date	2 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-10-31
Last registration	2024-04-05
Complete history	See info



Registration #1	2016-10-31	20 mi
Registration #2	2019-10-19	24.260 mi
Registration #3	2020-10-28	32.755 mi
Registration #4	2021-06-04	35.836 mi
Registration #5	2022-05-17	51.781 mi
Registration #6		
Registration #7		
Registration #8		
Registration #9		
Registration #10		
Registration #11		

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2120 mm
Height	1713 mm
Length	4644 mm
Wheel base	2774 mm
Kerb weight	1839 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1666805