



report date: 2024-03-28

General information

Make	VOLVO
Model	XC60 D4 SE AWD
Colour	Silver
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-02-25
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	15
Total items failed	5

MOT #13	2024-02-26 10:17
MOT test number	458814282736
Result	✓ Passed
Next expiry date	2025-02-25
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12	2024-02-26 10:17
MOT test number	761337296792
Result	✗ Failed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Pass with rectification	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11	2023-02-15 14:57
MOT test number	495226814142
Result	✓ Passed

**MOT #10**

2023-02-15 09:35

MOT test number

750740786341

Result

✗ Failed

Fail

Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #9

2022-02-24 09:49

MOT test number

849139480341

Result

✓ Passed

Advice

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8

2021-02-05 09:32

MOT test number

905315575727

Result

✓ Passed

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #7

2021-02-04 14:30

MOT test number

304275954234

Result

✗ Failed

Fail

Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail

Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Pass with rectification

Offside Front Headlamp aim too high (4.1.2 (a))

Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))



MOT #6	2020-02-21 09:07
MOT test number	434658644820
Result	✓ Passed
Advice	Nearside Front flexi brake pipe bracket insecure
MOT #5	2019-02-22 10:21
MOT test number	583940335271
Result	✓ Passed
MOT #4	2018-02-26 16:36
MOT test number	417154055503
Result	✓ Passed
MOT #3	2017-02-16 10:13
MOT test number	267037186349
Result	✓ Passed
MOT #2	2016-01-27 14:13
MOT test number	160139420930
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit 2.7mm (4.1.E.1)
Advice	Offside Front Inner Tyre worn close to the legal limit 2.1mm (4.1.E.1)
MOT #1	2015-02-17 12:28
MOT test number	986288145016
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
25 February 2025

Tax status	Valid until 1 August
Days left	95
MOT expiry date	25 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-03-29
Last registration	2024-02-26
Complete history	See info



Registration #1	2012-03-29	12 mi
Registration #2	2015-02-17	14.539 mi
Registration #3	2016-01-27	21.535 mi
Registration #4	2017-02-16	30.319 mi
Registration #5	2018-02-26	38.944 mi
Registration #6	2019-02-22	47.867 mi
Registration #7	2020-02-21	55.246 mi
Registration #8	2021-02-04	57.845 mi
Registration #9	2022-03-29	59.377 mi
Registration #10	2022-03-29	59.377 mi
Registration #11	2022-03-29	59.377 mi
Registration #12	2022-03-29	59.377 mi
Registration #13	2022-03-29	59.377 mi
Registration #14	2022-03-29	59.377 mi
Registration #15	2022-03-29	59.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1891 mm
Height	1713 mm
Length	4627 mm
Wheel base	2774 mm
Kerb weight	1840 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1162478