



report date: 2024-03-29

General information

Make	FORD
Model	FIESTA ECONETIC TDCI
Colour	Blue
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	204 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	88.3 mpg
Consumption combined	76.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-11
Pictures	12
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #16	2022-12-28 14:38
MOT test number	847725630385
Result	✓ Passed
Next expiry date	2024-01-14
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Advice Nearside Front All direction indicators slightly discoloured (4.4.3 (a))	

MOT #15	2022-01-15 16:47
MOT test number	763948048285
Result	✓ Passed

MOT #14	2022-01-05 17:54
MOT test number	243765872567
Result	✗ Failed
Fail Offside Front Service brake lagging in operation (1.2.1 (d))	
Fail Exhaust emissions exceed level of metered smoke for a non-turbo charged engine (8.2.2.2 (b))	
Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))	
Fail Front Brakes imbalanced across an axle by more than 50% Axle 1 (1.2.1 (b) (ii))	
Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))	
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #13	2020-12-18 17:41
MOT test number	680073268732
Result	✓ Passed

**MOT #12**

2020-12-18 10:58

MOT test number

615083194164

Result**✗ Failed**

- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Fail** Front Windscreen washer not working wiper blades blades not checked (3.5 (a))
- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail** Offside Headlamp aim not tested (4.1.2 (b))
- Fail** Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))
- Fail** Offside Front Direction indicator incorrect colour (4.4.3 (a))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #11

2019-12-28 13:46

MOT test number

827442462883

Result**✓ Passed**

- Advice** Nearside Front Inner Play in steering rack inner joint(s)

MOT #10

2019-12-23 14:19

MOT test number

474683285164

Result**✗ Failed**

- Fail** Windscreen washer not working (3.5 (a))
- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Inner Play in steering rack inner joint(s)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm inner edge (5.2.3 (e))

**MOT #9** 2018-12-21 17:54**MOT test number** 865310543528**Result** ✓ Passed**Minor** Front Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Few chips on windscreen**Minor** Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))**Advice** Engine cover and under tray fitted**MOT #8** 2017-12-23 17:16**MOT test number** 360872080909**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front both tyre wearing inner edge**Advice** Offside Rear Direction indicators have a product on the light source but not adversely affecting light output (1.4.A.2e)**Advice** Offside Rear cluster damaged**MOT #7** 2017-12-21 14:35**MOT test number** 482919121243**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front both tyre wearing inner edge**Fail** Offside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)**Advice** Offside Rear cluster damaged**Advice** Offside Rear Direction indicators have a product on the light source but not adversely affecting light output (1.4.A.2e)

**MOT #6** 2016-12-01 13:36**MOT test number** 218582367637**Result** ✓ Passed**Advice** Nearside Front Tyre outer sidewall damaged, no cord exposed.**Advice** Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Undertrays fitted obscuring and preventing inspection of some components**MOT #5** 2015-12-23 14:42**MOT test number** 661618115540**Result** ✓ Passed**Advice** Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside rear tyre has been driven on whilst flat**MOT #4** 2015-12-23 14:42**MOT test number** 786801790653**Result** ✗ Failed**Advice** Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Nearside rear tyre has been driven on whilst flat**Pass with rectification** Nearside Body has a sharp edge caused by damage Mirror casing damaged (6.1.C.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-12-09 14:38**MOT test number** 435623844319**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2014-12-09 14:38
MOT test number	729923044361
Result	✗ Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (8.2.3)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1	2013-06-29 14:56
MOT test number	979620183131
Result	✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EN10FFB
Plate since	2019-03-29
Current registration	EN10FFB
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-06-29
Last registration	2022-12-28
Complete history	See info



Registration #1	2010-06-29	18 mi
Registration #2	2013-06-29	50.719 mi
Registration #3	2014-12-09	59.513 mi
Registration #4	2015-12-23	62.606 mi
Registration #5	2015-12-23	62.606 mi
Registration #6	2016-12-01	69.282 mi
Registration #7	2017-12-21	73.165 mi
Registration #8	2017-12-23	73.220 mi
Registration #9	2018-12-21	81.213 mi
Registration #10	2019-06-29	95.277 mi
Registration #11	2019-06-29	95.277 mi
Registration #12	2019-06-29	95.277 mi
Registration #13	2019-06-29	95.277 mi
Registration #14	2019-06-29	95.277 mi
Registration #15	2019-06-29	95.277 mi
Registration #16	2019-06-29	95.277 mi
Registration #17	2019-06-29	95.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1722 mm
Height	1433 mm
Length	3950 mm
Wheel base	2489 mm
Kerb weight	1158 kg
Max. allowed weight	1545 kg

Additional information

Fuel tank capacity	43 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	9G63211
---------------	---------