



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	CLS CLS220 D AMG LINE PREMIUM
Colour	Silver
Year of manufacture	2016
Top speed	138 mph
0 - 60 mph	8.5 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	174 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	65.7 mpg
Consumption combined	57.7 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 2

Date	2021-09-16
Pictures	5
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-15
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-22
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	6
Total items failed	4

MOT #7	2023-12-06 10:07
MOT test number	794947355418
Result	✓ Passed
Next expiry date	2024-12-22
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #6	2023-12-06 10:07
MOT test number	605258154198
Result	✗ Failed
Pass with rectification	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #5	2022-12-23 09:13
MOT test number	483080588440
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

**MOT #4** 2021-12-20 12:28**MOT test number** 687176685921**Result** ✓ Passed**MOT #3** 2020-12-16 14:43**MOT test number** 172981817273**Result** ✓ Passed**MOT #2** 2020-12-15 14:02**MOT test number** 220544535509**Result** ✗ Failed

- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #1 2019-11-06 10:42**MOT test number** 590724111682**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
22 December 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	22 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	LO66LXZ
Plate since	2019-06-29
Current registration	LO66LXZ
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-12-31
Last registration	2023-12-06
Complete history	See info



Registration #1	2016-12-31	22 mi
Registration #2	2019-11-06	46.679 mi
Registration #3	2020-12-15	58.847 mi
Registration #4	2020-12-16	58.866 mi
Registration #5	2023-12-06	58.866 mi
Registration #6	2023-12-06	58.866 mi
Registration #7	2023-12-06	58.866 mi
Registration #8	2023-12-06	58.866 mi
Registration #9	2023-12-06	58.866 mi
Registration #10	2023-12-06	58.866 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	81%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1881 mm
Height	1418 mm
Length	4937 mm
Wheel base	2874 mm
Kerb weight	1790 kg
Max. allowed weight	2275 kg

Additional information

Fuel tank capacity	59 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	4
Number of axles	2
Engine number	65192433311329