



report date: 2024-03-29

## General information

Make	VOLVO
Model	XC70 D5 SE LUX AWD
Colour	Black
Year of manufacture	2011
Top speed	127 mph
0 - 60 mph	8.4 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	202 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg
CO2 emission	189 g/km
CO2 label	J





Internet history

Entry 1

Date	2022-03-11
Pictures	5
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-05-29
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	10
Total items failed	3

MOT #13	2023-05-18 08:12
MOT test number	594343542225
Result	✓ Passed
Next expiry date	2024-05-29

MOT #12	2022-05-30 13:53
MOT test number	397503062997
Result	✓ Passed

MOT #11	2022-05-27 14:17
MOT test number	692343551549
Result	✗ Failed
Fail	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #10	2021-10-18 09:25
MOT test number	646822934295
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #9	2020-10-12 15:58
MOT test number	269208658756
Result	✓ Passed

**MOT #8** 2019-10-15 12:29**MOT test number** 128319046129**Result** ✓ Passed**MOT #7** 2018-10-11 09:37**MOT test number** 626714886563**Result** ✓ Passed**MOT #6** 2017-10-13 09:01**MOT test number** 586050128306**Result** ✓ Passed**MOT #5** 2016-11-01 10:31**MOT test number** 605221112826**Result** ✓ Passed**Advice** Nearside Rear trailing arm bush rubber bonding beginning to separate**Advice** Offside Rear trailing arm bush rubber bonding separated**MOT #4** 2016-11-01 09:41**MOT test number** 388460680627**Result** ✗ Failed**Advice** Nearside Rear trailing arm bush rubber bonding beginning to separate**Advice** Offside Rear trailing arm bush rubber bonding separated**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #3** 2015-10-06 14:12**MOT test number** 455978988339**Result** ✓ Passed



MOT #2	2015-09-30 09:52
MOT test number	800138552284
Result	✗ Failed
Fail	Nearside Rear coil spring broken (2.4.C.1a)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2014-10-31 09:45
MOT test number	615874304349
Result	✓ Passed
Notice	Emissions emit low reading
Notice	Exhaust corroded
Notice	O/S/F marker light not working



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
29 May 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	29 May 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>AF11VJK</b>
Plate since	2019-03-29
Current registration	<b>AF11VJK</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-03-01
Last registration	2023-05-18
Complete history	<a href="#">See info</a>



Registration #1	2011-03-01	14 mi
Registration #2	2014-10-31	78.377 mi
Registration #3	2015-09-30	102.898 mi
Registration #4	2015-10-06	102.904 mi
Registration #5	2016-11-01	115.598 mi
Registration #6	2016-11-01	115.598 mi
Registration #7	2017-10-13	125.015 mi
Registration #8	2018-10-11	133.886 mi
Registration #9	2019-05-20	151.277 mi
Registration #10	2019-05-20	151.277 mi
Registration #11	2019-05-20	151.277 mi
Registration #12	2019-05-20	151.277 mi
Registration #13	2019-05-20	151.277 mi
Registration #14	2019-05-20	151.277 mi
Registration #15	2019-05-20	151.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1861 mm
Height	1604 mm
Length	4838 mm
Wheel base	2815 mm
Kerb weight	1895 kg
Max. allowed weight	2400 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	933852