





report date: 2024-03-29

General information

Make	MINI	
Model	MINI (R60) COOPER S ALL4	
Colour	Black	
Year of manufacture	2011	
Top speed	130 mph	
0 - 60 mph	7.9 seconds	
Gearbox	6 speed Manual	

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	42.2 mpg
CO2 emission	157 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-10-11

Pictures 26

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



EK11VGN report date: 2024-03-29

MOT history

MOT expiry date	2024-10-08
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	15
Total items failed	1

MOT #13		2023-10-05 16:57
MOT test	number	851798475457
Result		✓ Passed
Next expi	ry date	2024-10-08
Advice	Nearside Rear Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12		2022-10-07 08:48
MOT test	number	297154197986
Result		✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #11 2021-10-01 11:01 **MOT** test number 264580481222 Result ✓ Passed **Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d)) Advice Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i)) Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))

MOT #10

MOT test number

249155002516

Result

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9

MOT test number

Result

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

DANGEROUS Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

DANGEROUS Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

 MOT #8
 2019-08-03 11:34

 MOT test number
 859225802243

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #7	2018-08-06 15:59
MOT test number	906093064212
Result	✓ Passed
MOT #6	2017-09-01 07:42
MOT test number	266321710138
Result	✓ Passed
MOT #5	2016-07-14 08:52
MOT test number	621843594068
Result	✓ Passed
MOT #4	2015-07-25 11:10
MOT test number	225816105222
Result	✓ Passed
MOT #3	2014-07-21 09:39
MOT test number	299662304298
Result	✓ Passed
MOT #2	2013-07-29 09:02
MOT test number	166580113265
Result	✓ Passed
MOT #1	2013-07-26 16:32
MOT test number	367687803419
Result	★ Failed
Fail Nearside Rear Tyre has a lump, caused by separation or partial failure of its stru	ucture (4.1.D.1b)

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	8 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



EK11VGN report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

e when mistery	
For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	NK SIX
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



EK11VGN report date: 2024-03-29

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-03-31
Last registration	2023-10-05
Complete history	See info



Registration #1	2011-03-31	6 mi
Registration #2	2013-07-26	16.874 mi
Registration #3	2013-07-29	16.874 mi
Registration #4	2014-07-21	19.970 mi
Registration #5	2015-07-25	21.631 mi
Registration #6	2016-07-14	24.422 mi
Registration #7	2017-09-01	33.874 mi
Registration #8	2018-08-06	42.777 mi
Registration #9		11.777 es
Registration #10		77,777 44
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		11.777 ms

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Kerb weight	1380 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	47 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 12/12

Engine number

A574I961