



report date: 2024-03-29

General information

Make	AUDI
Model	TT TDI QUATTRO S LINE SPECIAL EDITION
Colour	White
Year of manufacture	2010
Top speed	140 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-09-21
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-28
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	19
Total items failed	16

MOT #17	2023-08-29 16:32
MOT test number	759195264374
Result	✓ Passed
Next expiry date	2024-08-28
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement NSR FRONT-MOST ARM INNER BUSH DETERIORATED (5.3.4 (a) (i))
Minor	Front Headlamp cleaning device inoperative (4.1.6 (a) (i))
Advice	Rear Brake pipe corroded, covered in grease or other material BOTH FRONT-REAR BRAKE PIPE REARMOST UNIONS CORRODED (1.1.11 (c))

**MOT #16**

2023-08-25 12:38

MOT test number

885329003972

Result**✗ Failed**

- Fail** Nearside Front Tyre has ply or cords exposed CUT TO CORDS (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge INNER EDGE ON LIMIT (5.2.3 (e))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Fail** Offside Rear Shock absorbers has negligible damping effect (5.3.2 (d))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm INNER EDGE (5.2.3 (e))
- Minor** Central Front Headlamp cleaning device inoperative (4.1.6 (a) (i))
- Fail** Central Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge INNER EDGE UNEVEN WEAR (5.2.3 (e))
- Fail** Nearside Rear Shock absorbers has negligible damping effect (5.3.2 (d))
- Advice** Central Front Items removed from driver's view prior to test
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #15

2022-08-24 10:37

MOT test number

404726217072

Result**✓ Passed**

**MOT #14**

2022-08-09 14:11

MOT test number

148971129325

Result**✗ Failed**

- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Offside Front Suspension rod ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Nearside Front Suspension rod ball joint excessively worn (5.3.4 (a) (i))

MOT #13

2021-08-28 11:15

MOT test number

720313806998

Result**✓ Passed****MOT #12**

2020-08-27 10:32

MOT test number

165873833963

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front discs pitted

MOT #11

2020-08-25 11:54

MOT test number

875907212759

Result**✗ Failed**

- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front discs pitted

**MOT #10** 2019-05-02 09:47**MOT test number** 625299551859**Result** ✓ Passed**MOT #9** 2018-05-02 12:49**MOT test number** 525597860993**Result** ✓ Passed**MOT #8** 2018-05-01 14:27**MOT test number** 649164401610**Result** ✗ Failed**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**MOT #7** 2017-03-17 09:46**MOT test number** 223952820261**Result** ✓ Passed**MOT #6** 2016-03-02 14:17**MOT test number** 779192687905**Result** ✓ Passed**MOT #5** 2016-03-01 09:48**MOT test number** 302046412600**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #4** 2015-03-11 09:20**MOT test number** 946700075077**Result** ✓ Passed

**MOT #3** 2014-04-01 14:11**MOT test number** 766031694080**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #2** 2014-02-27 11:29**MOT test number** 979938054060**Result** ✗ Failed**Fail** Offside Side repeater not working (1.4.A.2c)**Notice** Under-trays fitted obscuring some underside components**Pass with rectification** Windscreen has a sticker or other obstruction encroaching by more than 10mm within zone 'A' (8.3.1b)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #1** 2013-02-26 16:21**MOT test number** 186027753476**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
28 August 2024

Tax status		Valid until 1 October
Days left		155
MOT expiry date		28 August 2024
Full MOT history		See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	TT10SYE
Plate since	2019-09-29
Current registration	TT10SYE
Plate since	2019-09-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-03-19
Last registration	2023-08-29
Complete history	See info



Registration #1	2010-03-19	18 mi
Registration #2	2013-02-26	48.658 mi
Registration #3	2014-02-27	69.870 mi
Registration #4	2014-04-01	71.849 mi
Registration #5	2015-03-11	82.965 mi
Registration #6	2016-03-01	86.944 mi
Registration #7	2016-03-02	86.944 mi
Registration #8	2017-03-17	90.707 mi
Registration #9	2018-05-01	97.595 mi
Registration #10	2018-05-02	97.596 mi
Registration #11	2019-05-01	97.597 mi
Registration #12	2019-05-01	97.597 mi
Registration #13	2019-05-01	97.597 mi
Registration #14	2019-05-01	97.597 mi
Registration #15	2019-05-01	97.597 mi
Registration #16	2019-05-01	97.597 mi
Registration #17	2019-05-01	97.597 mi
Registration #18	2019-05-01	97.597 mi
Registration #19	2019-05-01	97.597 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1842 mm
Height	1352 mm
Length	4178 mm
Wheel base	2468 mm
Kerb weight	1360 kg
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	CBB 155263