




report date: 2024-03-29

General information

Make	CITROEN
Model	C2 CODE
Colour	Grey
Year of manufacture	2007
Top speed	126 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	143 Nm at 3.750 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	163 g/km
CO2 label	G






Internet history

Entry 2

Date	2022-02-25
Pictures	19
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-06
Pictures	5
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-03-03
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	59
Total items failed	3

MOT #202024-03-04 13:33

MOT test number886653306366

Result✓ Passed

Next expiry date2025-03-03

- Advice

Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor

Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))
- Advice

Offside Front Upper Macpherson strut mounting damaged but not seriously weakened mount (5.3.3 (b) (i))
- Advice

Covers over outer sills
- Minor

Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #19**

2024-02-23 15:07

MOT test number

102547921751

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Offside Front Upper Macpherson strut mounting damaged but not seriously weakened mount (5.3.3 (b) (i))
- MAJOR** Rear Exhaust system insecure one rear metal mount missing (6.1.2 (a))
- Advice** Covers over outer sills
- MAJOR** Offside Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill to under sills (7.1.1 (a) (i))
- MAJOR** Offside Front Direction indicator incorrect colour (4.4.3 (a))
- Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))
- MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- MAJOR** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Central Exhaust system insecure mount broken away from system (6.1.2 (a))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- MAJOR** Nearside Front Direction indicator incorrect colour (4.4.3 (a))
- Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- MAJOR** Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))



MOT #18	2023-02-16 15:29
MOT test number	300911447274
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #17	2023-02-08 09:46
MOT test number	329264572732
Result	✗ Failed
MAJOR	Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Minor	Nearside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
MAJOR	Track rod end ball joint has excessive play track rod to rack end loose (2.1.3 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
DANGEROUS	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #16	2022-03-03 20:35
MOT test number	717936403358
Result	✓ Passed
Advice	Nearside Front Inner Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #15	2022-01-25 17:40
MOT test number	465705261691
Result	✗ Failed
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #14**

2021-05-20 08:15

MOT test number

647650907581

Result

✓ Passed

Advice Offside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Play in steering rack inner joint(s)**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #13**

2021-05-20 08:15

MOT test number

853636062979

Result

✗ Failed

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Play in steering rack inner joint(s)**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**MOT #12**

2020-05-04 08:16

MOT test number

338325881270

Result

✓ Passed

MOT #11

2020-05-01 08:01

MOT test number

748850448167

Result

✗ Failed

MAJOR Fuel cap/sealing device missing (6.1.3 (b) (i))**Minor** Offside Front Brake hose slightly twisted flexible hose routed incorrectly and secured with a cable tie (1.1.12 (b) (i))

**MOT #10**

2018-12-07 15:22

MOT test number

588662403703

Result

✓ Passed

Minor

Nearside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Rear Coil spring corroded (5.3.1 (b) (i))

MOT #9

2017-12-08 13:10

MOT test number

440944058446

Result

✓ Passed

MOT #8

2016-12-09 16:10

MOT test number

542135176794

Result

✓ Passed

Advice

Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Advice

Nearside Steering rack gaiter deteriorated (2.2.D.2d)

MOT #7

2015-12-04 17:04

MOT test number

229152659155

Result

✓ Passed

Advice

Nearside rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)

Advice

Nearside Steering rack gaiter deteriorated (2.2.D.2d)

Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2015-12-04 17:04**MOT test number** 895912976738**Result** ✗ Failed

Advice Nearside rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)

Pass with rectification Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Steering rack gaiter deteriorated (2.2.D.2d)

MOT #5 2014-12-05 17:38**MOT test number** 218519434391**Result** ✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #4 2013-12-03 16:32**MOT test number** 417147533315**Result** ✓ Passed**MOT #3** 2012-12-06 16:17**MOT test number** 368211842364**Result** ✓ Passed**MOT #2** 2011-12-10 11:04**MOT test number** 295834541320**Result** ✓ Passed

Advice Offside Front Seat belt stitching slightly frayed (5.2.2b)



MOT #1	2010-12-09 17:24
MOT test number	472023240336
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2025

✓
MOT
Expires:
3 March 2025

Tax status	Valid until 1 September
Days left	490
MOT expiry date	3 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-12-11
Last registration	2024-03-04
Complete history	See info



Registration #1	2007-12-11	20 mi
Registration #2	2010-12-09	16.485 mi
Registration #3	2011-12-10	24.265 mi
Registration #4	2012-12-06	30.315 mi
Registration #5	2013-12-03	37.292 mi
Registration #6	2014-12-05	42.326 mi
Registration #7	2015-12-04	46.595 mi
Registration #8	2015-12-04	46.595 mi
Registration #9	2016-12-09	49.870 mi
Registration #10	2017-12-08	53.328 mi
Registration #11	2018-12-07	57.363 mi
Registration #12	2020-05-01	59.832 mi
Registration #13	2020-05-01	59.832 mi
Registration #14	2020-05-01	59.832 mi
Registration #15	2020-05-01	59.832 mi
Registration #16	2020-05-01	59.832 mi
Registration #17	2020-05-01	59.832 mi
Registration #18	2020-05-01	59.832 mi
Registration #19	2020-05-01	59.832 mi
Registration #20	2020-05-01	59.832 mi
Registration #21	2020-05-01	59.832 mi
Registration #22	2020-05-01	59.832 mi
Registration #23	2020-05-01	59.832 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1659 mm
Height	1474 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	1084 kg
Max. allowed weight	1415 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FX7P3266200