



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE DESIGN TDI BLUEMOTION TECHNOLOGY
Colour	White
Year of manufacture	2015
Top speed	112 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	113 g/km
CO2 label	C







Internet history

Entry 1

Date	2022-07-10
Pictures	18
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-19
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	9
Total items failed	1

MOT #9	2023-05-18 16:25
MOT test number	165393251694
Result	✓ Passed
Next expiry date	2024-05-19

MOT #8	2022-04-26 10:51
MOT test number	552548334160
Result	✓ Passed

MOT #7	2022-04-23 15:10
MOT test number	645867175502
Result	✗ Failed
MAJOR Offside Front Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))	

MOT #6	2021-04-23 14:58
MOT test number	110174647670
Result	✓ Passed

**MOT #5** 2021-04-23 09:58**MOT test number** 266269440100**Result** ✗ Failed**MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Nearside Side repeater light intensity significantly reduced (4.4.3 (a))**MOT #4** 2020-05-01 08:06**MOT test number** 892028945922**Result** ✓ Passed**Advice** Vehicle was too clean to trigger the smoke meter**Advice** Lower under tray and top covers fitted**MOT #3** 2020-05-01 08:06**MOT test number** 461163361245**Result** ✗ Failed**Advice** Vehicle was too clean to trigger the smoke meter**Pass with rectification** Nearside Outer Body component damaged and likely to cause injury door mirror casing damaged (6.2.1 (a) (i))**Advice** Lower under tray and top covers fitted**MOT #2** 2019-04-26 08:20**MOT test number** 485277263325**Result** ✓ Passed**Advice** Vehicle was too clean to trigger the smoke meter**Advice** Lower under tray and top covers fitted**MOT #1** 2018-04-23 12:57**MOT test number** 220953401392**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
19 May 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	19 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 CK15ZTF
Plate since	2019-03-29
Current registration	 CK15ZTF
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-05-20
Last registration	2023-05-18
Complete history	See info



Registration #1	2015-05-20	16 mi
Registration #2	2018-04-23	8.412 mi
Registration #3	2019-04-26	11.890 mi
Registration #4	2020-05-01	15.728 mi
Registration #5	2020-05-01	15.728 mi
Registration #6	2021-04-23	17.422 mi
Registration #7	2023-05-18	20.277 mi
Registration #8	2023-05-18	20.277 mi
Registration #9	2023-05-18	20.277 mi
Registration #10	2023-05-18	20.277 mi
Registration #11	2023-05-18	20.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	90%
Pedestrian	53%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1808 mm
Height	1486 mm
Length	4278 mm
Wheel base	2537 mm
Kerb weight	1361 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	4
Engine number	CAYCAG2518