



RENAULT




report date: 2024-03-28

General information

Make	RENAULT
Model	KANGOO EXPRESSION 16V E4
Colour	Grey
Year of manufacture	2008
Top speed	101 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	94 BHP
Max. torque	148 Nm at 3.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.3 mpg
CO2 emission	190 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-10-27
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-01
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	39
Total items failed	9

MOT #18	2023-10-02 10:03
MOT test number	698033141919
Result	✓ Passed
Next expiry date	2024-10-01
Advice	Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Items removed from driver's view prior to test
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #17	2022-11-04 12:21
MOT test number	470450165815
Result	✓ Passed

MOT #16	2021-11-01 15:41
MOT test number	968067301181
Result	✓ Passed

MOT #15	2020-08-07 13:08
MOT test number	830616513865
Result	✓ Passed

Advice Play in steering rack inner joint(s)

**MOT #14**

2020-08-07 08:13

MOT test number

299481400212

Result**✗ Failed****Pass with rectification**

Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice

Play in steering rack inner joint(s)

Fail

Central Exhaust has a major leak of exhaust gases (6.1.2 (a))

MOT #13

2019-07-25 08:26

MOT test number

923203267361

Result**✓ Passed****Advice**

Nearside Front anti roll bar linkage rubber deteriorating

Advice

Small exhaust blow

Advice

Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice

Offside Front anti roll bar linkage rubber deteriorating

MOT #12

2018-07-25 13:43

MOT test number

191530655678

Result**✓ Passed****Advice**

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice

Power steering pipe/hose has slight seepage (2.1.5 (a))

**MOT #11**

2018-07-25 09:38

MOT test number

575931520478

Result**✗ Failed****Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Power steering pipe/hose has slight seepage (2.1.5 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Fuel pipe leaking (6.1.3 (b) (i))**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10**

2017-08-01 08:18

MOT test number

443948737445

Result**✓ Passed****Advice** Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front tyre scrubbing on inner edge**Advice** Nearside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear tyre has cracks along sidewall but not down to ply**Advice** Offside Front tyre scrubbing on inner edge**MOT #9**

2016-08-05 10:52

MOT test number

312580758373

Result**✓ Passed****Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear rear parking (secondary) brake grabbing slightly (3.7.B.6b)

**MOT #8** 2016-07-28 09:03**MOT test number** 301362596144**Result** ✗ Failed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Rear Exhaust has a major leak of exhaust gases back box and middle section (7.1.2)**Advice** Nearside Rear rear parking (secondary) brake grabbing slightly (3.7.B.6b)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Front constant velocity joint is excessively worn (2.5.C.1b)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #7** 2015-07-14 13:59**MOT test number** 765615995146**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Both rear tyres slight perishing**MOT #6** 2015-07-14 09:18**MOT test number** 817975395134**Result** ✗ Failed**Notice** Both rear tyres slight perishing**Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2014-08-08 08:49**MOT test number** 797510824230**Result** ✓ Passed

**MOT #4** 2013-04-08 13:20**MOT test number** 487288893098**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-05-10 12:44**MOT test number** 728491432189**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2011-06-09 13:33**MOT test number** 407520861195**Result** ✓ Passed**MOT #1** 2011-06-09 12:39**MOT test number** 827970361126**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
1 October 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	1 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-28
Current registration	*****
Plate since	2023-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-07-17
Last registration	2023-10-02
Complete history	See info



Registration #1	2008-07-17	20 mi
Registration #2	2011-06-09	8.658 mi
Registration #3	2011-06-09	8.658 mi
Registration #4	2012-05-10	12.198 mi
Registration #5	2013-04-08	15.619 mi
Registration #6	2014-08-08	17.526 mi
Registration #7	2015-07-14	20.198 mi
Registration #8	2015-07-14	20.201 mi
Registration #9	2016-07-28	22.921 mi
Registration #10	2016-08-05	22.931 mi
Registration #11	2016-08-05	22.931 mi
Registration #12	2016-08-05	22.931 mi
Registration #13	2016-08-05	22.931 mi
Registration #14	2016-08-05	22.931 mi
Registration #15	2016-08-05	22.931 mi
Registration #16	2016-08-05	22.931 mi
Registration #17	2016-08-05	22.931 mi
Registration #18	2016-08-05	22.931 mi
Registration #19	2016-08-05	22.931 mi
Registration #20	2016-08-05	22.931 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2031 mm
Height	1825 mm
Length	4035 mm
Wheel base	2605 mm
Kerb weight	1120 kg
Max. allowed weight	1645 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D024868