



report date: 2024-03-28

General information

Make	VAUXHALL
Model	AGILA SE
Colour	Blue
Year of manufacture	2014
Top speed	106 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	93 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	56.5 mpg
Consumption combined	49.6 mpg
CO2 emission	131 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-05-26
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-11
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	8
Total items failed	1

MOT #10	2023-12-12 11:50
MOT test number	584565820942
Result	✓ Passed
Next expiry date	2024-12-11
Advice	Handbrake has travel
Advice	Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #9	2022-12-10 11:29
MOT test number	689084502745
Result	✓ Passed

MOT #8	2021-12-10 16:20
MOT test number	577587858277
Result	✓ Passed

**MOT #7** 2021-12-10 13:23**MOT test number** 443352233852**Result** ✗ Failed**MAJOR** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #6** 2020-09-23 13:34**MOT test number** 693029572368**Result** ✓ Passed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #5** 2020-09-23 13:34**MOT test number** 402011991261**Result** ✗ Failed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Pass with rectification** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #4** 2019-10-03 11:18**MOT test number** 572964992504**Result** ✓ Passed**MOT #3** 2018-10-16 07:53**MOT test number** 972893166188**Result** ✓ Passed**MOT #2** 2017-11-28 14:55**MOT test number** 806008778581**Result** ✓ Passed



MOT #1	2017-02-15 12:37
MOT test number	615363286628
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
11 December 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	11 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	ML14BHN
Plate since	2019-03-28
Current registration	ML14BHN
Plate since	2019-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-04-28
Last registration	2023-12-12
Complete history	See info



Registration #1	2014-04-28	23 mi
Registration #2	2017-02-15	12.760 mi
Registration #3	2017-11-28	16.213 mi
Registration #4	2018-10-16	19.228 mi
Registration #5	2019-10-03	23.866 mi
Registration #6	2020-09-23	25.742 mi
Registration #7	2021-09-23	25.777 mi
Registration #8	2022-09-23	25.777 mi
Registration #9	2023-09-23	25.777 mi
Registration #10	2023-09-23	25.777 mi
Registration #11	2023-09-23	25.777 mi
Registration #12	2023-09-23	25.777 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	1065 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	K12B - 1810397LUY