





L M

General information	
Make	RENAULT
Model	SCENIC DYNAMIQUE TOMTOM LUXE ENERGY DCI S/S
Colour	Bronze
Year of manufacture	-
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP	0 < 101 A	LABEL UNKNOWN
Cylinders	4	101 - 120 ^B	
Fuel type	Diesel	121 - 140 P	
Consumption city	48.7 mpg	141 - 165 F	
Consumption extra urban	64.2 mpg	166 - 185 H	
Consumption combined	57.6 mpg	J 186 - 225 K	

225+





Internet history

Entry	1

Date Pictures 2021-02-04

10

Listing price

View report



source: autoonline.co.uk



MOT history

MOT #11	2023-03-24 08:33
MOT test number	577530537206
Result	✓ Passed
Next expiry date	2024-04-14
Advice Nearside Front Tyre slightly damaged Oute	r sidewall scuffed (5.2.3 (d) (ii))
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Nearside Front Tyre worn close to legal lim	it/worn on edge (5.2.3 (e))

MOT #10	2023-03-22 11:57
MOT test number	524707578999
Result	× Failed
Advice Rear Brake pad(s) wearing thin BORDERLINE (1.1.13 (a) (ii))	
Advice Nearside Front Tyre slightly damaged Outer sidewall scuffed (5.2.3 (d) (ii))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
DANGEROUS Offside Rear Tyre has a tear, caused by separation or partial failure of (d) (ii))	f its structure (5.2.3
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre slightly damaged Outer sidewall scuffed (5.2.3 (d) (ii))	
DANGEROUSNearside Rear Tyre has a tear, caused by separation or partial failure(d) (ii))	of its structure (5.2.3
Pass with rectificationEngine MIL inoperative or indicates a malfunction (8.2.2.2)	(g))
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

МОТ #9	2022-03-29 12:11
MOT test number	210660152063
Result	✓ Passed
Advice Offside Play in steering rack inner joint(s) advise further investigation	





MOT #8		2021-04-15 06:37
MOT test number		145447253340
Result		✓ Passed
MOT #7		2021-04-15 06:37
MOT test number		368456364456
Result		🗙 Failed
Pass with rectification	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #6	2020-06-09 16:20
MOT test number	928064234628
Result	✓ Passed
Advice Offside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #5	2019-06-25 10:12
MOT test number	518204002149
Result	✓ Passed

MOT #4	2018-06-13 14:04
MOT test number	410285512749
Result	✓ Passed
Advice Engine covers and under trays fitted	
Advice Items removed from driver's view prior to test	

MOT #3		2017-06-15 11:32
MOT test number		707272958537
Result		✓ Passed
Advice Rear brake	disc worn, pitted or scored, but not seriously weakened both (3.5.1)	i)
Advice Rear Brake	pad(s) wearing thin (3.5.1g)	





MOT #2	2016-06-16 11:34
MOT test number	387367002295
Result	✓ Passed
MOT #1	2015-06-19 12:32
MOT test number	227510175176
Result	✓ Passed





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second se	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	
Reduction a	
Plane anna	
Current registration	
Current registration Plate since	





Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-07-06
Last registration	2023-03-24
Complete history	See info



Registration #1	2012-07-06	23 mi
Registration #2	2015-06-19	33.173 mi
Registration #3	2016-06-16	41.200 mi
Registration #4	2017-06-15	49.835 mi
Registration #5	2018-06-13	54.259 mi
Registration #6	2019-06-25	57.729 mi
Registration #7	2020-06-09	60.926 mi
Registration #8		11.777 est
Registration #9		
Registration #5		10.317 est
Registration #10		11.227 es
-		11.777 es
Registration #10		00.000 460 01.000 460 00.000 460 01.000 460

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1845 mm
Height	1640 mm
Length	4366 mm
Wheel base	2697 mm
Kerb weight	1434 kg
Max. allowed weight	1967 kg
Additional information	
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number CarCheck.co.uk	D044692 page 11/11