



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV-4 D-4D XT4
Colour	Black
Year of manufacture	2006
Top speed	112 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	310 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	173 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-10-16
Pictures	13
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2022-11-01
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	22
Total items failed	7

MOT #18	2021-11-02 09:04
MOT test number	921302126666
Result	✓ Passed
Next expiry date	2022-11-01

MOT #17	2021-01-11 10:50
MOT test number	625199868675
Result	✓ Passed
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #16	2021-01-11 10:50
MOT test number	896906407269
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Pass with rectification	Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #15** 2020-01-03 09:29**MOT test number** 834488957189**Result** ✓ Passed**Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Central Exhaust has a minor leak of exhaust gases silencer (6.1.2 (a))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**MOT #14** 2019-01-10 13:49**MOT test number** 783762452240**Result** ✓ Passed**Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**MOT #13** 2019-01-10 11:28**MOT test number** 370346099616**Result** ✗ Failed**Fail** Offside Rear Anti-roll bar linkage insecure and impairing directional stability (5.3.3 (a) (ii))**Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))**Fail** Nearside Rear Anti-roll bar linkage insecure and impairing directional stability (5.3.3 (a) (ii))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**MOT #12** 2018-01-08 08:50**MOT test number** 862248880651**Result** ✓ Passed

**MOT #11** 2018-01-03 15:34**MOT test number** 671200901242**Result** ✗ Failed**Fail** Offside Front Shock absorber has a serious fluid leak (2.7.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Park brake travel**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**MOT #10** 2017-04-28 15:02**MOT test number** 349027254497**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #9** 2016-04-28 09:22**MOT test number** 453574256542**Result** ✓ Passed**MOT #8** 2015-05-02 08:49**MOT test number** 218372725180**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2015-03-23 09:28**MOT test number** 237762285031**Result** ✓ Passed**MOT #6** 2014-03-12 12:14**MOT test number** 119701074017**Result** ✓ Passed**MOT #5** 2013-03-19 12:01**MOT test number** 185618573464**Result** ✓ Passed**MOT #4** 2012-03-09 09:12**MOT test number** 115679062010**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #3** 2011-03-04 11:54**MOT test number** 599703361058**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2010-03-08 14:09**MOT test number** 124167160088**Result** ✓ Passed**Notice** Windscreen stone chipped**MOT #1** 2009-02-23 10:32**MOT test number** 821154659034**Result** ✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	<b>GJ06HDY</b>
Plate since	2019-09-29
Current registration	<b>GJ06HDY</b>
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-03-11
Last registration	2021-11-02
Complete history	<a href="#">See info</a>



Registration #1	2006-03-11	8 mi
Registration #2	2009-02-23	61.019 mi
Registration #3	2010-03-08	77.621 mi
Registration #4	2011-03-04	86.914 mi
Registration #5	2012-03-09	98.704 mi
Registration #6	2013-03-19	109.233 mi
Registration #7	2014-03-12	119.076 mi
Registration #8	2015-03-23	124.299 mi
Registration #9	2015-05-02	124.384 mi
Registration #10	2016-04-28	130.814 mi
Registration #11	2016-04-28	130.814 mi
Registration #12	2016-04-28	130.814 mi
Registration #13	2016-04-28	130.814 mi
Registration #14	2016-04-28	130.814 mi
Registration #15	2016-04-28	130.814 mi
Registration #16	2016-04-28	130.814 mi
Registration #17	2016-04-28	130.814 mi
Registration #18	2016-04-28	130.814 mi
Registration #19	2016-04-28	130.814 mi
Registration #20	2016-04-28	130.814 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1815 mm
Height	1685 mm
Length	4395 mm
Wheel base	2560 mm
Kerb weight	1585 kg
Max. allowed weight	2190 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	2AD0006099