



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI STARTLINE BLUEMOTION TECHNOLOGY
Colour	White
Year of manufacture	2015
Top speed	106 mph
0 - 100 km/h	13.4 seconds
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 kW / 102 HP / 101 BHP
Max. torque	250 Nm at 2.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	58.9 mpg
Consumption combined	54.3 mpg
CO2 emission	134 g/km
CO2 label	E






Internet history

Entry 1

Date	2022-02-19
Pictures	13
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-04-19
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	4
Total items failed	7

MOT #9	2023-04-03 15:38
MOT test number	179664946161
Result	✓ Passed
Next expiry date	2024-04-19

MOT #8	2023-03-29 16:28
MOT test number	966119634199
Result	✗ Failed
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
Fail	Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge worn edges (5.2.3 (e))
Fail	Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))

MOT #7	2022-04-20 10:06
MOT test number	866272046902
Result	✓ Passed

MOT #6	2021-04-06 12:50
MOT test number	352960158537
Result	✓ Passed

**MOT #5** 2020-07-13 15:15**MOT test number** 524964987215**Result** ✓ Passed**MOT #4** 2020-07-13 09:21**MOT test number** 570978931474**Result** ✗ Failed

**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Fail** Offside Rear Service brake lagging in operation (1.2.1 (d))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #3** 2019-06-07 08:54**MOT test number** 954893683687**Result** ✓ Passed**MOT #2** 2019-06-07 07:44**MOT test number** 783070750665**Result** ✗ Failed

**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #1** 2018-06-20 09:27**MOT test number** 199973019488**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 August 2024

✗  
**MOT**  
  
Expired:  
19 April 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	19 April 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>BL15ZPB</b>
Plate since	2019-03-29
Current registration	 <b>BL15ZPB</b>
Plate since	2019-03-29

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-07-06
Last registration	2023-04-03
Complete history	<a href="#">See info</a>



Registration #1	2015-07-06	11 mi
Registration #2	2018-06-20	38.732 mi
Registration #3	2019-06-07	55.565 mi
Registration #4	2019-06-07	55.565 mi
Registration #5	2020-07-13	72.758 mi
Registration #6	2020-07-13	72.759 mi
Registration #7	2020-07-13	72.759 mi
Registration #8	2020-07-13	72.759 mi
Registration #9	2020-07-13	72.759 mi
Registration #10	2020-07-13	72.759 mi
Registration #11	2020-07-13	72.759 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	2062 mm
Height	1836 mm
Length	4876 mm
Wheel base	3 mm
Kerb weight	1566 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	2
Number of axles	2
Engine number	CAYDBF5177