



report date: 2024-03-28

General information

Make	FORD
Model	C-MAX TITANIUM TDCI
Colour	Silver
Year of manufacture	2008
Top speed	122 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-10-01
Pictures	24
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-09-29
Pictures	23
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-10-08
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	16
Total items failed	16

MOT #20	2023-09-29 13:43
MOT test number	574381979139
Result	✓ Passed
Next expiry date	2024-10-08
Advice	Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

MOT #19	2023-09-29 12:47
MOT test number	483547145900
Result	✗ Failed
Advice	Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
Fail	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

MOT #18	2022-10-03 14:24
MOT test number	693419101509
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge close/perishing (5.2.3 (e))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #17**

2022-10-03 09:10

**MOT test number**

547515977756

**Result****✗ Failed****Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge close/perishing (5.2.3 (e))**MOT #16**

2021-10-06 15:41

**MOT test number**

196487182077

**Result****✓ Passed****Advice** Offside Rear Tyre slightly damaged (5.2.3 (d) (ii))**MOT #15**

2021-10-05 13:42

**MOT test number**

827697036570

**Result****✗ Failed****Fail** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Horn not working (7.7 (a))**Advice** Offside Rear Tyre slightly damaged (5.2.3 (d) (ii))**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**MOT #14** 2020-10-09 07:56**MOT test number** 251338327323**Result** ✓ Passed**MOT #13** 2020-10-01 09:33**MOT test number** 107448418403**Result** ✗ Failed**Fail** Nearside Headlamp insecure (4.1.1 (c))**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Minor** Offside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #12** 2019-07-12 08:50**MOT test number** 559529646676**Result** ✓ Passed**MOT #11** 2018-06-29 09:20**MOT test number** 117522222475**Result** ✓ Passed**MOT #10** 2018-06-29 08:07**MOT test number** 825947627752**Result** ✗ Failed**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #9** 2017-07-21 08:08**MOT test number** 544825197414**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2016-07-27 08:55**MOT test number** 417951514812**Result** ✓ Passed**MOT #7** 2015-07-23 10:15**MOT test number** 128124605254**Result** ✓ Passed**MOT #6** 2015-07-23 10:15**MOT test number** 816764405287**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #5** 2014-07-28 17:23**MOT test number** 915969504262**Result** ✓ Passed**MOT #4** 2014-07-28 09:41**MOT test number** 329779704464**Result** ✗ Failed**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #3** 2013-09-18 11:23**MOT test number** 585851863278**Result** ✓ Passed



MOT #2	2012-09-25 10:28
MOT test number	688839262248
Result	✓ Passed

MOT #1	2011-09-30 11:00
MOT test number	307973271247
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
8 October 2024

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	336
<b>MOT expiry date</b>	8 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-09-30
Last registration	2023-09-29
Complete history	<a href="#">See info</a>



Registration #1	2008-09-30	8 mi
Registration #2	2011-09-30	23.281 mi
Registration #3	2012-09-25	30.048 mi
Registration #4	2013-09-18	36.494 mi
Registration #5	2014-07-28	42.945 mi
Registration #6	2014-07-28	42.945 mi
Registration #7	2015-07-23	49.691 mi
Registration #8	2016-07-27	57.615 mi
Registration #9	2017-07-21	64.260 mi
Registration #10	2018-06-29	70.375 mi
Registration #11	2018-06-29	70.375 mi
Registration #12	2019-06-29	76.490 mi
Registration #13	2019-06-29	76.490 mi
Registration #14	2019-06-29	76.490 mi
Registration #15	2019-06-29	76.490 mi
Registration #16	2019-06-29	76.490 mi
Registration #17	2019-06-29	76.490 mi
Registration #18	2019-06-29	76.490 mi
Registration #19	2019-06-29	76.490 mi
Registration #20	2019-06-29	76.490 mi
Registration #21	2019-06-29	76.490 mi
Registration #22	2019-06-29	76.490 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1897 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	8S89767