



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	KANGOO SL 17 DCI 70
Colour	White
Year of manufacture	-
Gearbox	5 speed Manual

Engine & fuel consumption

Power	65 BHP
Max. torque	170 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-04-27
Pictures	26
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #26	2024-01-19 17:02
MOT test number	188538662683
Result	✓ Passed
Next expiry date	2025-01-18
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #25	2024-01-19 12:17
MOT test number	582269034737
Result	✗ Failed
MAJOR	Nearside Headlamp aim too low (4.1.2 (a))
MAJOR	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
MAJOR	Offside Headlamp aim too low (4.1.2 (a))
MAJOR	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))

MOT #24	2022-11-02 16:18
MOT test number	271031223391
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #23** 2022-11-02 09:34**MOT test number** 425945158566**Result** ✗ Failed**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MAJOR** Offside Windscreen washer not working (3.5 (a))**MAJOR** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Windscreen washer not working (3.5 (a))**MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #22** 2021-10-19 08:05**MOT test number** 903099944490**Result** ✓ Passed**MOT #21** 2020-10-22 14:29**MOT test number** 820598148744**Result** ✓ Passed**Advice** Nearside Play in steering rack inner joint(s)

**MOT #20**

2020-10-22 08:05

MOT test number

686165633628

Result**✗ Failed**

- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Nearside Parking brake inoperative on one side (1.4.1 (a))

MOT #19

2019-10-29 10:02

MOT test number

938969604068

Result**✓ Passed**

- Advice** Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #18

2018-10-17 14:10

MOT test number

885376616244

Result**✓ Passed**

- Advice** Oil leak, but not excessive Engine (8.4.1 (a) (i))
- Advice** Nsrear and osrear tyres surface cracks on tread

**MOT #17** 2018-10-17 08:57**MOT test number** 653426372192**Result** ✗ Failed**Advice** Oil leak, but not excessive Engine (8.4.1 (a) (i))**MAJOR** Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))**MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Nsrear and osrear tyres surface cracks on tread**MAJOR** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**MAJOR** Offside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))**MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #16** 2017-10-24 09:09**MOT test number** 436446650958**Result** ✓ Passed**MOT #15** 2017-10-24 08:42**MOT test number** 989634774876**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #14** 2016-10-21 14:56**MOT test number** 210487745624**Result** ✓ Passed

**MOT #13** 2016-10-21 08:56**MOT test number** 255145062400**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #12** 2015-10-20 08:51**MOT test number** 667772819467**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened Inner face (3.5.1i)**Advice** Slight play in inner steering rack joints**MOT #11** 2014-10-21 10:25**MOT test number** 666204394271**Result** ✓ Passed**MOT #10** 2013-10-18 09:47**MOT test number** 336891193285**Result** ✓ Passed**MOT #9** 2012-10-17 16:11**MOT test number** 286121392257**Result** ✓ Passed**MOT #8** 2012-10-17 11:04**MOT test number** 328281892423**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage insecure (2.4.G.1)

**MOT #7** 2011-11-03 12:00**MOT test number** 677077101365**Result** ✓ Passed**Advice** Nearside Steering system has slight free play detected at steering wheel (2.2.A.1b)**MOT #6** 2011-11-02 11:36**MOT test number** 348436001380**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Steering system has slight free play detected at steering wheel (2.2.A.1b)**MOT #5** 2010-12-29 13:00**MOT test number** 971463760386**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2009-12-30 09:40**MOT test number** 424764469363**Result** ✓ Passed**MOT #3** 2009-01-10 09:59**MOT test number** 160530319031**Result** ✓ Passed**Notice** Slight damage to o/s/r lamp



MOT #2	2008-01-08 11:59
MOT test number	750588208061
Result	✓ Passed
Notice	O/s/r light unit cracked not showing white light or sharp edges

MOT #1	2008-01-07 15:23
MOT test number	480527408077
Result	✗ Failed
Notice	O/s/r light unit cracked not showing white light or sharp edges
Fail	Front brake disc in such a condition that it is seriously weakened (3.5.1i)
Notice	Wipers split but clearing screen
Fail	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
Fail	Offside Rear Registration plate lamp not working (1.1.C.1d)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2005-01-10
Last registration	2024-01-19
Complete history	See info



Registration #1	2005-01-10	16 mi
Registration #2	2008-01-07	49.857 mi
Registration #3	2008-01-08	49.857 mi
Registration #4	2009-01-10	57.265 mi
Registration #5	2009-12-30	65.273 mi
Registration #6	2010-12-29	70.827 mi
Registration #7	2011-11-02	74.231 mi
Registration #8	2011-11-03	74.231 mi
Registration #9	2012-10-17	77.845 mi
Registration #10	2012-10-17	77.845 mi
Registration #11	2013-10-18	82.570 mi
Registration #12	2014-10-21	87.039 mi
Registration #13	2015-10-20	91.222 mi
Registration #14	2016-10-21	95.181 mi
Registration #15	2016-10-21	95.181 mi
Registration #16	2016-10-21	95.181 mi
Registration #17	2016-10-21	95.181 mi
Registration #18	2016-10-21	95.181 mi
Registration #19	2016-10-21	95.181 mi
Registration #20	2016-10-21	95.181 mi
Registration #21	2016-10-21	95.181 mi
Registration #22	2016-10-21	95.181 mi
Registration #23	2016-10-21	95.181 mi
Registration #24	2016-10-21	95.181 mi
Registration #25	2016-10-21	95.181 mi
Registration #26	2016-10-21	95.181 mi

Registration #27	2025-25-25	25,252,252
Registration #28	2025-25-25	25,252,252

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1672 mm
Kerb weight	1055 kg
Max. allowed weight	1675 kg

Additional information

Number of seats	2
Number of axles	2
Engine number	DA16244