



RENAULT

STI4CZH

report date: 2024-03-28

General information

Make	RENAULT
Model	CLIO DYNAMIQUE MEDIANAV ENERGY TCE S/S
Colour	Black
Year of manufacture	2014
Top speed	113 mph
0 - 60 mph	12.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	135 Nm at 2.500 rpm
Engine capacity	899 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-04
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2025-04-13
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	24
Total items failed	12

**MOT #11** 2024-03-27 14:44**MOT test number** 773380816984**Result** ✓ Passed**Next expiry date** 2025-04-13**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2023-04-14 08:26**MOT test number** 413459378110**Result** ✓ Passed**MOT #9** 2021-10-25 11:58**MOT test number** 888249171064**Result** ✓ Passed**Advice** Offside Front Brake pipe corroded, covered in grease or other material metal brake pipe to flexi (1.1.11 (c))**Advice** Covers and under-trays fitted

**MOT #8** 2021-10-25 08:22**MOT test number** 389025086588**Result** ✗ Failed**Advice** Covers and under-trays fitted**Fail** Brake lever has insufficient reserve travel (1.1.2 (a))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Coolant level close to minimum mark**Fail** Offside Front Suspension arm pin or bush excessively worn lower arm rear bush (5.3.4 (a) (i))**Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))**Advice** Offside Front Brake pipe corroded, covered in grease or other material metal brake pipe to flex (1.1.11 (c))**MOT #7** 2020-11-02 15:53**MOT test number** 280062961075**Result** ✓ Passed**MOT #6** 2019-05-01 14:19**MOT test number** 960617927197**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge tyre edges scrubbed / bald (5.2.3 (e))

**MOT #5**

2019-04-30 14:02

**MOT test number**

950321723668

**Result**

✗ Failed

**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge tyre edges scrubbed / bald (5.2.3 (e))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))**MOT #4**

2018-03-28 07:23

**MOT test number**

864190888062

**Result**

✓ Passed

**Advice** Under trays fitted**Advice** Front brake disc worn, pitted or scored, but not seriously weakened worn (3.5.1i)**MOT #3**

2018-03-09 16:18

**MOT test number**

240916043010

**Result**

✓ Passed

**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Nail in tyre**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

**MOT #2**

2018-03-09 10:43

**MOT test number**

509712513896

**Result****✗ Failed**

**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear (2.4.G.2)

**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure also badly perished (4.1.D.1b)

**Advice** Coolant low

**Fail** Parking brake: efficiency below requirements (3.7.B.7)

**Pass with rectification** Nearside Headlamp aim too low (1.8)

**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

**Advice** Offside Rear brake sticky

**Advice** Child Seat fitted not allowing full inspection of adult belt

**Advice** Offside Rear Nail in tyre

**MOT #1**

2017-03-31 13:37

**MOT test number**

848355249284

**Result****✓ Passed**

**Advice** Child Seat fitted not allowing full inspection of adult belt

**Advice** Offside Rear brake sticky braking system may require adjustment or repair



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
13 April 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	338
<b>MOT expiry date</b>	13 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-03-31
Last registration	2024-03-27
Complete history	<a href="#">See info</a>



Registration #1	2014-03-31	26 mi
Registration #2	2017-03-31	46.821 mi
Registration #3	2018-03-09	64.148 mi
Registration #4	2018-03-09	64.155 mi
Registration #5	2018-03-28	65.131 mi
Registration #6	2019-04-30	70.850 mi
Registration #7	2019-05-01	70.850 mi
Registration #8	2019-05-01	70.850 mi
Registration #9	2019-05-01	70.850 mi
Registration #10	2019-05-01	70.850 mi
Registration #11	2019-05-01	70.850 mi
Registration #12	2019-05-01	70.850 mi
Registration #13	2019-05-01	70.850 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	89%
Pedestrian	66%
Safety systems	99%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1732 mm
Height	1488 mm
Length	4062 mm
Wheel base	2589 mm
Kerb weight	980 kg
Max. allowed weight	1588 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	U165424