



HONDA



report date: 2024-03-29

General information

Make	HONDA
Model	CR-Z I-VTEC IMA SPORT
Colour	Red
Year of manufacture	2010
Top speed	124 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	145 Nm at 4.800 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	117 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-12-19
Pictures	2
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-16
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	25
Total items failed	2

MOT #142024-03-06 13:03

MOT test number412736244852

Result✓ Passed

Next expiry date2025-03-16

- Minor

Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor

Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice

Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement beam bush (5.3.4 (a) (i))
- Minor

Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice

Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement beam bush (5.3.4 (a) (i))
- Minor

Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #13**

2023-02-28 11:38

MOT test number

925359153862

Result

✓ Passed

Advice Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bushes (Both Sides) (5.3.4 (a) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2.5mm & cracking (5.2.3 (e))

Minor Front Lower Suspension arm ball joint dust cover severely deteriorated Both sides (5.3.4 (b) (i))

MOT #12

2023-02-28 11:38

MOT test number

673009493751

Result

✗ Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2.5mm & cracking (5.2.3 (e))

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bushes (Both Sides) (5.3.4 (a) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Front Lower Suspension arm ball joint dust cover severely deteriorated Both sides (5.3.4 (b) (i))

Pass with rectification Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #11

2022-03-17 12:17

MOT test number

128745818299

Result

✓ Passed

**MOT #10** 2022-03-16 12:25**MOT test number** 626426099062**Result** ✗ Failed**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #9** 2021-11-15 11:23**MOT test number** 171454220246**Result** ✓ Passed**MOT #8** 2020-12-10 10:49**MOT test number** 352882998141**Result** ✓ Passed**MOT #7** 2019-11-27 10:21**MOT test number** 398147593849**Result** ✓ Passed**MOT #6** 2018-11-27 09:18**MOT test number** 789166061417**Result** ✓ Passed**MOT #5** 2017-11-24 08:41**MOT test number** 283852050854**Result** ✓ Passed**Advice** Valve stem slightly damaged all 4 perished (4.1.D.1e)**MOT #4** 2016-11-25 08:34**MOT test number** 120052871484**Result** ✓ Passed



MOT #3	2015-11-16 08:50
MOT test number	649142315201
Result	✓ Passed

MOT #2	2014-11-19 09:29
MOT test number	549343124326
Result	✓ Passed
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2013-11-16 10:34
MOT test number	826720023345
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
16 March 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	16 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	C
Single payment (12 months)	£ 25,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 26,25,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1		
Date		
Category		
Type		
Damage 2		
Date		
Category		
Type		



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-12-06
Last registration	2024-03-06
Complete history	See info



Registration #1	2010-12-06	26 mi
Registration #2	2013-11-16	16.708 mi
Registration #3	2014-11-19	23.478 mi
Registration #4	2015-11-16	28.224 mi
Registration #5	2016-11-25	34.041 mi
Registration #6	2017-11-24	39.976 mi
Registration #7	2018-11-27	46.725 mi
Registration #8	2019-11-27	50.560 mi
Registration #9	2020-05-20	55.377 mi
Registration #10	2021-05-20	55.377 mi
Registration #11	2022-05-20	55.377 mi
Registration #12	2023-05-20	55.377 mi
Registration #13	2024-03-06	55.377 mi
Registration #14	2024-03-06	55.377 mi
Registration #15	2024-03-06	55.377 mi
Registration #16	2024-03-06	55.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	80%
Pedestrian	71%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2014 mm
Height	1395 mm
Length	4080 mm
Wheel base	2425 mm
Kerb weight	1198 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	LEA1 1016382