



TOYOTA

S852SNG

report date: 2024-03-29

General information

Make	TOYOTA
Model	LANDCRUISER ESTATE GX TD
Colour	Silver
Year of manufacture	1998
Top speed	99 mph
0 - 60 mph	14.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	295 Nm at 2.400 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	21.4 mpg
Consumption extra urban	30.1 mpg
Consumption combined	26.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-21
Pictures	12
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-06
MOT pass rate	67 %
MOT passed	18
Failed MOT tests	9
Total advice items	28
Total items failed	27

MOT #27 2023-09-25 10:19

MOT test number 560432322254

Result ✓ Passed

Next expiry date 2024-10-06

Advice Rear Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))

Advice Offside Front Suspension component ball joint has slight play (5.3.4 (a) (i))

MOT #26 2022-10-07 08:44

MOT test number 361938367916

Result ✓ Passed

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #25 2021-09-11 11:02

MOT test number 259587785381

Result ✓ Passed

**MOT #24**

2021-08-27 07:28

MOT test number

251476221262

Result**✗ Failed**

- Fail** Nearside Front Lower Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))
- Fail** Offside Parking brake inoperative on one side very low (1.4.1 (a))
- Fail** Central Exhaust has a major leak of exhaust gases box holed (6.1.2 (a))
- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #23

2020-12-21 13:58

MOT test number

310165208411

Result**✓ Passed**

- Minor** Nearside Front Lower Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Offside Front Lower Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside parking brake lower reading than n/s
- Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #22** 2019-05-29 12:30**MOT test number** 742741157532**Result** ✓ Passed**Advice** Reverse lamps inop**Advice** Fuel Pipe/s corroded**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Tyre slightly damaged/cracking or perishing all (5.2.3 (d) (ii))**MOT #21** 2018-06-07 12:48**MOT test number** 675901945433**Result** ✓ Passed**MOT #20** 2018-06-05 12:41**MOT test number** 128155385646**Result** ✗ Failed**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**Fail** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))**MOT #19** 2017-06-06 11:14**MOT test number** 473007152900**Result** ✓ Passed**Advice** Brake pipe slightly corroded (3.6.B.2c)**MOT #18** 2016-06-06 11:27**MOT test number** 503096461565**Result** ✓ Passed

**MOT #17** 2015-05-13 14:53**MOT test number** 976343835158**Result** ✓ Passed**MOT #16** 2015-05-12 11:27**MOT test number** 165132235161**Result** ✗ Failed**Fail** Offside Outer Front Anti-roll bar attachment bracket/mounting insecure (2.4.G.1)**Fail** Offside Rear Suspension spring mounting prescribed area is excessively corroded (2.4.A.3)**MOT #15** 2014-04-24 07:58**MOT test number** 455164414167**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #14** 2014-04-17 11:09**MOT test number** 786677604128**Result** ✗ Failed**Fail** Rear fog lamp not working (1.3.2b)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Fail** Rear parking brake recording little or no effort (3.7.B.6a)**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Parking brake: efficiency below requirements (3.7.C.1b)**MOT #13** 2013-04-29 14:20**MOT test number** 569149213136**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #12**

2013-04-26 11:01

MOT test number

208326813120

Result**✗ Failed****Fail** Front position lamp(s) not working (1.1.A.3b)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Shock absorber has a serious fluid leak (2.7.3)**MOT #11**

2012-05-04 08:07

MOT test number

819235922117

Result**✓ Passed****Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #10**

2012-05-02 09:10

MOT test number

228393522183

Result**✗ Failed****Fail** Brake pipe leaking (3.6.A.1)**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Registration plate lamp not working (1.1.C.1d)**Fail** Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #9**

2011-05-06 11:28

MOT test number

235006521433

Result**✓ Passed**

**MOT #8** 2011-05-04 10:59**MOT test number** 835054221107**Result** ✗ Failed**Fail** Nearside Front Brake hose excessively deteriorated (3.6.B.4d)**Fail** Offside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Fail** Offside Front Brake hose excessively deteriorated (3.6.B.4d)**MOT #7** 2010-05-13 11:20**MOT test number** 650703730146**Result** ✓ Passed**MOT #6** 2010-05-11 09:26**MOT test number** 974191930102**Result** ✗ Failed**Fail** Registration plate lamp not working (1.1.5c)**Fail** Brake pipe excessively corroded (3.6.B.2c)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #5** 2009-05-12 08:27**MOT test number** 974012439122**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



MOT #4	2009-05-06 08:50
MOT test number	813176129134
Result	✗ Failed
Fail	Exhaust has a major leak of exhaust gases (7.1.2)
Fail	Shock absorber has a serious fluid leak (2.7.3)
Fail	Anti-roll bar rubber mounting deteriorated resulting in excessive movement (2.4.G.2)
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #3	2008-04-16 11:03
MOT test number	144107208135
Result	✓ Passed

MOT #2	2007-03-09 13:26
MOT test number	764738467039
Result	✓ Passed

MOT #1	2006-02-07 12:32
MOT test number	554758836049
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
6 October 2024

Tax status	Valid until 1 October
-------------------	-----------------------

Days left	155
------------------	-----

MOT expiry date	6 October 2024
------------------------	----------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	29
First mileage registration	1998-08-01
Last registration	2023-09-25
Complete history	See info



Registration #1	1998-08-01	16 mi
Registration #2	2006-02-07	72.674 mi
Registration #3	2007-03-09	83.144 mi
Registration #4	2008-04-16	96.972 mi
Registration #5	2009-05-06	107.545 mi
Registration #6	2009-05-12	107.546 mi
Registration #7	2010-05-11	122.609 mi
Registration #8	2010-05-13	122.609 mi
Registration #9	2011-05-04	61.134 mi
Registration #10	2011-05-06	61.134 mi
Registration #11	2012-05-02	144.583 mi
Registration #12	2012-05-04	144.583 mi
Registration #13	2013-04-26	150.395 mi
Registration #14	2013-04-29	150.398 mi
Registration #15	2014-04-17	156.620 mi
Registration #16	2015-05-01	161.134 mi
Registration #17	2016-05-01	161.134 mi
Registration #18	2017-05-01	161.134 mi
Registration #19	2018-05-01	161.134 mi
Registration #20	2019-05-01	161.134 mi
Registration #21	2020-05-01	161.134 mi
Registration #22	2021-05-01	161.134 mi
Registration #23	2022-05-01	161.134 mi
Registration #24	2023-05-01	161.134 mi
Registration #25	2024-05-01	161.134 mi
Registration #26	2025-05-01	161.134 mi

Registration #27	2025-25-25	25,252,442
Registration #28	2025-25-25	25,252,442
Registration #29	2025-25-25	25,252,442

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1875 mm
Length	4750 mm
Wheel base	2675 mm

Additional information

Fuel tank capacity	90 l
Fuel delivery	Indirect Injection
Number of doors	5
Number of axles	2
Engine number	1KZ0631270