



report date: 2024-03-28

General information

Make	MAZDA
Model	MX-5 SPORT
Colour	Grey
Year of manufacture	2004
Top speed	130 mph
0 - 60 mph	8.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	144 BHP
Max. torque	168 Nm at 5.000 rpm
Engine capacity	1.839 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.7 mpg
Consumption extra urban	39.2 mpg
Consumption combined	31.7 mpg
CO2 emission	215 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-06-06
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-04-26
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	36
Total items failed	6

MOT #20 2023-04-18 09:15

MOT test number 958867673528

Result ✓ Passed

Next expiry date 2024-04-26

Advice Rear Vehicle structure is corroded but structural rigidity is not significantly reduced both inner sills/arches corroded (6.1.1 (c) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Minor Front Headlamp lens slightly defective both headlamps - lens dull/scratched (4.1.1 (b) (i))

MOT #19 2023-04-18 09:15

MOT test number 717168652238

Result ✗ Failed

Advice Rear Vehicle structure is corroded but structural rigidity is not significantly reduced both inner sills/arches corroded (6.1.1 (c) (i))

Minor Front Headlamp lens slightly defective both headlamps - lens dull/scratched (4.1.1 (b) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #18** 2022-04-27 14:22**MOT test number** 471508034576**Result** ✓ Passed**Advice** Offside Rear brake caliper has signs of break fluid residue around caliper unit**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**MOT #17** 2022-04-26 13:35**MOT test number** 300318180684**Result** ✗ Failed**Fail** Exhaust has a major leak of exhaust gases mid to rear section exhaust (6.1.2 (a))**Advice** Offside Rear brake caliper has signs of break fluid residue around caliper unit**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**MOT #16** 2021-04-27 14:30**MOT test number** 719877217841**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened All (1.1.14 (a) (ii))**Minor** Offside Front Tyre obviously under inflated (5.2.3 (l))**MOT #15** 2019-09-06 09:48**MOT test number** 713363687868**Result** ✓ Passed**Advice** Exhaust corroded

**MOT #14** 2018-08-06 10:00**MOT test number** 438901447398**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Surface corrosion offside rear outer sill and sill end**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #13** 2017-08-09 12:55**MOT test number** 373785119844**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Seat belt anchorage prescribed area is corroded but not considered excessive outer sill (5.2.6)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #12** 2017-08-07 11:13**MOT test number** 802436715620**Result** ✗ Failed**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Seat belt anchorage prescribed area is corroded but not considered excessive outer sill (5.2.6)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear Seat belt anchorage prescribed area is excessively corroded outer sill (5.2.6)

**MOT #11** 2016-07-30 08:55**MOT test number** 135503820814**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #10** 2015-04-02 12:36**MOT test number** 597022995044**Result** ✓ Passed**Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)**Notice** Osf brake discs corroded on inner edge -----surface corrosion both outer sills**MOT #9** 2014-02-20 16:01**MOT test number** 155661954424**Result** ✓ Passed**Notice** Nail in nearside rear tyre**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2013-02-05 15:50**MOT test number** 277716533007**Result** ✓ Passed**MOT #7** 2012-02-06 11:08**MOT test number** 805107032051**Result** ✓ Passed

**MOT #6** 2011-02-23 16:36**MOT test number** 285394751026**Result** ✓ Passed**MOT #5** 2010-07-26 15:14**MOT test number** 180097300284**Result** ✓ Passed**Advice** Nearside Rear Valve stem slightly damaged (4.1.D.1e)**Advice** Offside Rear Valve stem slightly damaged (4.1.D.1e)**MOT #4** 2009-06-08 11:20**MOT test number** 334639259141**Result** ✗ Failed**Advice** Front brake disc slightly pitted (3.5.1h)**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Handbrake lever high**MOT #3** 2009-06-08 11:20**MOT test number** 112569059176**Result** ✓ Passed**Advice** Front brake disc slightly pitted (3.5.1h)**Notice** Handbrake lever high**MOT #2** 2008-06-12 10:26**MOT test number** 990264368184**Result** ✓ Passed



MOT #1	2007-06-27 10:52
MOT test number	283338277409
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✗
MOT
Expired:
26 April 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	26 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2004-07-30
Last registration	2023-04-18
Complete history	See info



Registration #1	2004-07-30	14 mi
Registration #2	2007-06-27	12.467 mi
Registration #3	2008-06-12	18.890 mi
Registration #4	2009-06-08	22.556 mi
Registration #5	2010-07-26	29.069 mi
Registration #6	2011-02-23	30.648 mi
Registration #7	2012-02-06	34.123 mi
Registration #8	2013-02-05	39.817 mi
Registration #9	2014-02-20	44.671 mi
Registration #10	2015-04-02	48.150 mi
Registration #11	2016-07-30	50.509 mi
Registration #12	2016-09-20	51.377 mi
Registration #13	2016-10-20	51.377 mi
Registration #14	2016-11-20	51.377 mi
Registration #15	2016-12-20	51.377 mi
Registration #16	2017-01-20	51.377 mi
Registration #17	2017-02-20	51.377 mi
Registration #18	2017-03-20	51.377 mi
Registration #19	2017-04-20	51.377 mi
Registration #20	2017-05-20	51.377 mi
Registration #21	2017-06-20	51.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1680 mm
Height	1225 mm
Length	3975 mm
Wheel base	2265 mm
Kerb weight	1100 kg
Max. allowed weight	1315 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	BP 567876