

Ford



General information

Make	FORD
Model	KA TITANIUM
Colour	Blue
Year of manufacture	2015
Top speed	99 mph
0 - 100 km/h	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	51 kW / 69 HP / 68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	115 g/km
CO2 label	С







Internet history

Entry 1

Date

2021-10-25

Pictures

Listing price

View report

17



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-17
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	13
Total items failed	1

MOT #7		2023-09-29 13:59
MOT test	number	951120406288
Result		✓ Passed
Next expi	ry date	2024-10-17
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excess	ive movement (5.3.4 (a)
Advice	Nearside Front Road wheel slightly distorted $(5.2.2 (c) (i))$	
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in exce	ssive movement (5.3.4
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Rear Coil spring corroded Both (5.3.1 (b) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn on edges	(5.2.3 (e))

MOT #6	2022-10-11 09:54
MOT test number	192404298878
Result	✓ Passed
MOT #5	2021-10-06 16:19
MOT test number	515082086634

Result

✓ Passed





MOT #4		2020-10-15 15:35
MOT test	number	625521636394
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii)))

MOT #3		2020-10-15 15:35
MOT test number		960447357681
Result		🗙 Failed
Pass with rectifica	tion Nearside Windscreen wiper does not cl	lear the windscreen effectively (3.4 (b)
Advice Offside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))		
Advice Nearside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))		

MOT #2	2019-10-18 14:38
MOT test number	857664328836
Result	🗸 Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #1	2018-08-31 08:07
MOT test number	665591488895
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 November 2024	✓ MOT Expires: 17 October 2024
Tax status	Valid until 1 November
Days left	185
MOT expiry date	17 October 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERM
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	7
Carrent registration	
Plate since	
Exercised considerations	
Carriers registration	
Plate since	





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-08-10
Last registration	2023-09-29
Complete history	<u>See info</u>



Registration #1	2015-08-10	6 mi
Registration #2	2018-08-31	9.758 mi
Registration #3	2019-10-18	12.600 mi
Registration #4	2020-10-15	17.567 mi
Registration #5	2020-10-15	17.567 mi
Registration #6		11.117 esi
Registration #7		11.177 esi
Registration #8		11.117 esi
Registration #9		10.107 mil

More info >





Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	840 kg
Additional information	
Fuel tank capacity	35 I
Number of axles	2
Engine number	1361424