



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | FORD |
| Model | FOCUS CC2 |
| Colour | Purple |
| Year of manufacture | 2009 |
| Top speed | 130 mph |
| 0 - 60 mph | 10.3 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 143 BHP |
| Max. torque | 185 Nm at 4.500 rpm |
| Engine capacity | 1.999 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 26.6 mpg |
| Consumption extra urban | 49.6 mpg |
| Consumption combined | 37.7 mpg |
| CO2 emission | 179 g/km |
| CO2 label | I |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-01-30 |
| Pictures | 1 |
| Listing price | View report |



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-11-29 |
| MOT pass rate | 81 % |
| MOT passed | 13 |
| Failed MOT tests | 3 |
| Total advice items | 23 |
| Total items failed | 2 |

| | |
|------------------|---|
| MOT #16 | 2023-11-30 09:59 |
| MOT test number | 723469009475 |
| Result | ✓ Passed |
| Next expiry date | 2024-11-29 |
| Advice | Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) |
| Minor | Nearside Rear Tyre obviously under inflated (5.2.3 (l)) |
| Advice | Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) |

| | |
|-----------------|---|
| MOT #15 | 2022-11-18 13:12 |
| MOT test number | 605902853848 |
| Result | ✓ Passed |
| Advice | Nearside Front Non obligatory mirror damaged |
| Advice | Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i)) |

**MOT #14**

2022-11-17 11:37

MOT test number

658967106275

Result**✗ Failed****Advice** Nearside Front Non obligatory mirror damaged**Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**DANGEROUS** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #13**

2021-09-02 11:12

MOT test number

349876038491

Result**✓ Passed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #12**

2020-09-17 08:21

MOT test number

788355812997

Result**✓ Passed****MOT #11**

2019-11-12 13:55

MOT test number

882122855748

Result**✓ Passed****Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #10** 2018-11-07 11:56**MOT test number** 434549663253**Result** ✓ Passed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #9 2018-11-07 11:56**MOT test number** 307991009785**Result** ✗ Failed

Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #8 2017-11-17 13:55**MOT test number** 472038272203**Result** ✓ Passed**MOT #7** 2016-11-03 16:29**MOT test number** 859999252101**Result** ✓ Passed**MOT #6** 2015-11-03 11:58**MOT test number** 828057187936**Result** ✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2014-11-04 14:04**MOT test number** 176498004399**Result** ✓ Passed**MOT #4** 2014-03-12 12:27**MOT test number** 597311474052**Result** ✓ Passed**MOT #3** 2014-03-12 12:27**MOT test number** 158871774002**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2013-03-19 17:00**MOT test number** 427418073020**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2012-03-07 12:46**MOT test number** 565357862010**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this FORD had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 17 |
| First mileage registration | 2009-05-10 |
| Last registration | 2023-11-30 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2009-05-10 | 25 mi |
| Registration #2 | 2012-03-07 | 15.510 mi |
| Registration #3 | 2013-03-19 | 24.125 mi |
| Registration #4 | 2014-03-12 | 32.998 mi |
| Registration #5 | 2014-11-04 | 36.873 mi |
| Registration #6 | 2015-11-03 | 39.901 mi |
| Registration #7 | 2016-11-03 | 42.834 mi |
| Registration #8 | 2017-11-17 | 45.351 mi |
| Registration #9 | 2018-11-07 | 47.504 mi |
| Registration #10 | 2019-05-20 | 50.000 mi |
| Registration #11 | 2020-05-20 | 55.000 mi |
| Registration #12 | 2021-05-20 | 60.000 mi |
| Registration #13 | 2022-05-20 | 65.000 mi |
| Registration #14 | 2023-05-20 | 70.000 mi |
| Registration #15 | 2024-05-20 | 75.000 mi |
| Registration #16 | 2025-05-20 | 80.000 mi |
| Registration #17 | 2026-05-20 | 85.000 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1991 mm |
| Height | 1448 mm |
| Length | 4509 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1543 kg |
| Max. allowed weight | 1950 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 2 |
| Number of seats | 4 |

Engine number

9R32501