





General information

| Make | FIAT |
|---------------------|---------------------------------|
| Model | 500L MULTIJET TREKKING DUALOGIC |
| Colour | Grey |
| Year of manufacture | 2015 |
| Top speed | 98 mph |
| 0 - 60 mph | 16.1 seconds |
| Gearbox | 5 speed automatic |

Engine & fuel consumption

| Power | 85 BHP |
|-------------------------|---------------------|
| Max. torque | 200 Nm at 1.500 rpm |
| Engine capacity | 1.248 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 60.1 mpg |
| Consumption extra urban | 72.4 mpg |
| Consumption combined | 67.3 mpg |
| CO2 emission | 109 g/km |
| CO2 label | В |







Internet history

| Entry | 1 |
|-------|---|
| | |

Date Pictures 2022-04-07

45

Listing price

View report



source: cargurus.co.uk



MOT history

| MOT expiry date | 2025-04-22 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 8 |
| Failed MOT tests | 2 |
| Total advice items | 11 |
| Total items failed | 0 |

| MOT #10 | 2024-04-04 08:46 |
|------------------|------------------|
| MOT test number | 375721822917 |
| Result | ✓ Passed |
| Next expiry date | 2025-04-22 |

| MOT #9 | | 2023-04-19 09:17 |
|----------|--|------------------|
| MOT test | number | 850090331867 |
| Result | | ✓ Passed |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #8 | 2022-04-23 11:50 |
|-----------------|------------------|
| MOT test number | 612019682580 |
| Result | ✓ Passed |





| MOT #7 | 2022-04-22 13:37 |
|----------------------------|---|
| MOT test | |
| Result | × Failed |
| DANGER (d) (ii)) | OUS Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 |
| Advice | Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| MAJOR | Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |

| MOT #6 | 2021-08-23 15:52 |
|-----------------|------------------|
| MOT test number | 752187082059 |
| Result | ✓ Passed |

| MOT #5 | | 2021-08-20 11:58 |
|----------|--|------------------|
| MOT test | number | 155176115738 |
| Result | | 🗙 Failed |
| MAJOR | Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) | |
| MAJOR | Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) | |
| DANGER | OUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) | |

| MOT #4 | 2020-09-15 09:24 |
|-----------------|------------------|
| MOT test number | 155616058241 |
| Result | ✓ Passed |
| | |
| МОТ #3 | 2020-08-12 11:54 |
| MOT test number | 861712333394 |

Result

🗸 Passed



| Μ | W65GGZ |
|---|-------------------------|
| | report date: 2024-03-29 |

| MOT #2 | 2019-09-05 08:39 |
|---|------------------|
| MOT test number | 932800788720 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2018-09-19 11:51 |
| MOT test number | 489832832339 |
| Result | ✓ Passed |
| Advice Items removed from driver's view prior to test | |



mw65GGZ report date: 2024-03-29

Tax & MOT check

| | √ Taxed | | √ мот |
|---------------------------------|------------|----------------------------------|---------------------|
| Tax due: 1 April 2025 | | Expires: 22 April 2025 | |
| Tax status | | | Valid until 1 April |
| Days left | | | 336 |
| MOT expiry date | | | 22 April 2025 |
| Full MOT history | | | See MOT history |
| Tax calculation | | | |
| Vehicle class | | 49 | |
| Band | | В | |

| Band | В |
|---|----------------|
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|----------|
| Date | FEIDO |
| Category | 4. ARMPE |
| Туре | |
| Damage 2 | AMPL |
| | F Stores |
| Date | 1.E |
| Category | ante |
| Туре | |

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 |





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second s | |
|---|-------------|
| *********** | |
| ******** | |
| ******* | |
| ********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this FIAT had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | More info > |





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 12 |
| First mileage registration | 2015-10-27 |
| Last registration | 2024-04-04 |
| Complete history | See info |



| Registration #1 | 2015-10-27 | 11 mi |
|------------------|------------|------------|
| Registration #2 | 2018-09-19 | 1.467 mi |
| Registration #3 | 2019-09-05 | 6.315 mi |
| Registration #4 | 2020-08-12 | 20.937 mi |
| Registration #5 | 2020-09-15 | 22.741 mi |
| Registration #6 | 2021-08-20 | 47.494 mi |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.117 esi |
| Registration #10 | | 11.117 est |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 11.777 est |





Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 94% |
| Children | 78% |
| Pedestrian | 65% |
| Safety systems | 71% |
| Overall rating | 83% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 2018 mm |
| Height | 1679 mm |
| Length | 4270 mm |
| Kerb weight | 1320 kg |
| Max. allowed weight | 1855 kg |
| Additional information | |
| Fuel tank capacity | 50 I |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles CarCheck.co.uk | 2 page 12/12 |

Engine number

5504097