





report date: 2024-01-16

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T28 TDI P/V HIGHLINE BMT
Colour	White
Year of manufacture	2017
Top speed	98 mph
0 - 100 km/h	11.5 seconds
0 - 60 mph	15.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 kW / 150 HP / 101 BHP
Max. torque	340 Nm at 1.500 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G



CarCheck.co.uk page 1/11



SG67VPU
report date: 2024-01-16

Internet history

Entry 1

Date 2021-06-30

Pictures 33

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



Advice

Advice

Advice

SG67VPU

report date: 2024-01-16

MOT history	
MOT expiry date	2024-07-07
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	6
Total items failed	3
MOT #5	2023-06-15 11:34
MOT test number	557895655917
Result	✓ Passed
Next expiry date	2024-07-07
MOT #4	2022-07-02 09:19
MOT test number	651242601773
Result	✓ Passed
MOT #3	2021-07-08 11:34
MOT test number	454566177966
Result	✓ Passed
MOT #2	2020-09-18 15:27
MOT test number	285341995420
Result	✓ Passed

CarCheck.co.uk page 3/11

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Nearside Rear Tyre worn close to legal limit/worn on edge 205/65/16c (5.2.3 (e))



Advice

SG67VPU

report date: 2024-01-16

2020-09-18 09:15 **MOT #1 MOT test number** 682071261803 Result × Failed Fail Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i)) **Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 205/65/16c (5.2.3 (e)) Fail Rear Reversing lamp inoperative (4.6.1 (a)) Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i)) Fail

Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/11



report date: 2024-01-16

Tax & MOT check



Tax status	Valid until 1 July
Days left	114
MOT expiry date	7 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/11



report date: 2024-01-16

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1


Date

Category
Type

Damage 2

Date
Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



SG67VPU
report date: 2024-01-16

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-01-16

Owner history For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this VOLKSWAGEN had different number plates. mber of plates -More info >

CarCheck.co.uk page 8/11



report date: 2024-01-16

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 9/11



report date: 2024-01-16

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-09-30
Last registration	2023-06-15
Complete history	See info



Registration #1	2017-09-30	13 mi
Registration #2	2020-09-18	41.234 mi
Registration #3	2020-09-18	41.234 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-01-16

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	79%
Children	74%
Pedestrian	32%
Safety systems	57%
Overall rating	66%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1990 mm
Length	4892 mm
Wheel base	3000 mm
Kerb weight	1942 kg
Max. allowed weight	2800 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack co. uk	nago 11/1:

CarCheck.co.uk page 11/11

Number of seats	3
Number of axles	2
Engine number	CXGB047001