



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	VELOSTER GDI
Colour	Red
Year of manufacture	2013
Top speed	125 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	137 BHP
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.9 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	148 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-10-30
Pictures	35
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-27
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	20
Total items failed	1

MOT #10 2023-07-28 14:58

MOT test number 200898296462

Result ✓ Passed

Next expiry date 2024-07-27

- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Covers fitted obstructing view
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, but not excessively both (1.1.14 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

MOT #9 2022-07-28 12:36

MOT test number 533738616752

Result ✓ Passed

- Advice** Central Front Upper Items removed from driver's view prior to test

**MOT #8** 2021-07-08 07:35**MOT test number** 674901236868**Result** ✓ Passed

- Advice** Offside Front Tyre slightly damaged (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #7 2021-07-05 07:40**MOT test number** 406381700375**Result** ✗ Failed

- MAJOR** Nearside Headlamp aim too low (4.1.2 (a))
- Advice** Offside Front Tyre slightly damaged (5.2.3 (d) (ii))
- MAJOR** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- MAJOR** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))
- MAJOR** Offside Headlamp aim too low (4.1.2 (a))
- MAJOR** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- MAJOR** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #6 2020-07-08 14:11**MOT test number** 427190012897**Result** ✓ Passed

**MOT #5** 2019-10-17 10:14**MOT test number** 697553888904**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #4** 2018-09-11 16:04**MOT test number** 237879098432**Result** ✓ Passed**Advice** Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))**MOT #3** 2017-09-28 10:06**MOT test number** 544397335225**Result** ✓ Passed**MOT #2** 2017-09-28 10:06**MOT test number** 260495705013**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #1** 2016-09-19 15:44**MOT test number** 488094269323**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
27 July 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	27 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-11-27
Last registration	2023-07-28
Complete history	See info



Registration #1	2013-11-27	11 mi
Registration #2	2016-09-19	11.009 mi
Registration #3	2017-09-28	22.287 mi
Registration #4	2017-09-28	22.287 mi
Registration #5	2018-09-11	29.818 mi
Registration #6	2019-10-17	35.806 mi
Registration #7	2020-05-20	35.806 mi
Registration #8	2020-05-20	35.806 mi
Registration #9	2020-05-20	35.806 mi
Registration #10	2020-05-20	35.806 mi
Registration #11	2020-05-20	35.806 mi
Registration #12	2023-07-28	35.806 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	89%
Pedestrian	49%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1399 mm
Length	4220 mm
Wheel base	2650 mm
Kerb weight	1236 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	4

Engine number	G4FDDU436506
---------------	--------------