





report date: 2024-03-28

General information

Make	FORD
Model	ECOSPORT ZETEC
Colour	Grey
Year of manufacture	2018
Top speed	111 mph
0 - 100 km/h	12.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	92 kW / 125 HP / 123 BHP
Max. torque	170 Nm at 1.400 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	45.6 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

Emter.	1
Entry	т.

Entry 1	
Date	2021-06-30
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-05-14
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	17
Total items failed	2

MOT #6		2024-04-23 11:46
MOT test	number	755733881458
Result		✓ Passed
Next expi	ry date	2025-05-14
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt		
Advice	Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	

MOT #5		2024-04-23 07:57
MOT test	number	111679739813
Result		X Failed
Advice	Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Fail Front Inner Brake pad(s) worn down to wear indicator both side inner pads (1.1.13 (a) (i))		
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt		
Advice Front Brake disc worn, pitted or scored, but not seriously weakened both sides very lipped (1.1.14 (a) (ii))		

CarCheck.co.uk page 3/12



MOT #4 2023-05-05 08:33

MOT test number 571422563184

Result \rightarrow Passed

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated slight leak (6.1.7

(g) (i))

Advice Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #3 2023-05-05 08:33

MOT test number 532778632548

Result × Failed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Pass with rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated slight leak (6.1.7

(g) (i))

MOT #2 2022-05-10 13:50

MOT test number 905455533719

Result ✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/12



MOT #1 2021-05-06 14:13

MOT test number 289399488079

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	14 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12




CV18ZHR

report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report if	
THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NK AND
Plate since	
Current registration	NK AIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-05-15
Last registration	2024-04-23
Complete history	See info



Registration #1	2018-05-15	8 mi
Registration #2	2021-05-06	16.592 mi
Registration #3		11.777 es
Registration #4	2022-05-10	25.597 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	93%
Children	77%
Pedestrian	58%
Safety systems	55%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1653 mm
Length	4096 mm
Wheel base	2519 mm
Kerb weight	1280 kg
Max. allowed weight	1725 kg

Additional information

Fuel tank capacity	52 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/:

Number of axles2Engine numberJY35649