





General information

Make	VOLVO
Model	V70 D2 ES
Colour	Grey
Year of manufacture	2013
Top speed	115 mph
0 - 60 mph	12.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	115 BHP
Max. torque	270 Nm at 2.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	67.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С







Internet history

Entry 1

Date Pictures 2021-07-17

46

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-03
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	11
Total items failed	4

MOT #11	2023-08-04 10:27
MOT test number	916262417859
Result	✓ Passed
Next expiry date	2024-08-03

MOT #10	2022-09-30 08:39
MOT test number	650358572045
Result	✓ Passed
Advice Rear Coil spring corroded Both sides N/S/R and O/S/R (5.3.1 (b) (i))	
Advice Offside Front Nail in tyre	
Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)))

МОТ #9		2021-10-01 11:32
MOT test	number	486073661298
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	





MOT #8	2021-03-10 09:28
MOT test number	767096110577
Result	✓ Passed
MOT #7	2020-03-06 12:40
MOT test number	43524444136
Result	✓ Passed

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice

MOT #6		2019-03-14 16:14
MOT test	number	151537379261
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Under trays fitted as standard unable to fully inspect	

MOT #5	2018-03-09 10:55
MOT test number	311342257534
Result	✓ Passed

MOT #4		2018-03-09 10:55
MOT test number		273646304298
Result		🗙 Failed
Pass with rectification	Nearside Front Headlamp aim too low (1.8)	
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)	
Pass with rectification	Offside Front Front position lamp(s) not working (1.1.A.3b)	





МОТ #3		2017-02-17 15:42
MOT test number		812965588914
Result		✓ Passed
MOT #2		2017-02-17 15:42
MOT test number		349427350414
Result		🗙 Failed
Pass with rectification	Nearside Front Front position lamp(s) not working (1.1.A.3b)	
MOT #1		2016-02-29 12:43
MOT test number		803517441892
Result		✓ Passed



Tax & MOT check

Tax due: 1 August 2024	✓ Taxed	Expires: 3 August 2024	✓ мот
I August 2024		5 August 2024	
Tax status			Valid until 1 August
Days left			94
MOT expiry date			3 August 2024
Full MOT history			<u>See MOT history</u>
Tax calculation			
Vehicle class		49	

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4. ALANPE
Туре	
Damage 2	AMPL
	F Store
Date	1. E
Category	ame
Туре	

Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Current registration Plate since	





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >





Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-03-12
Last registration	2023-08-04
Complete history	See info



Registration #1	2013-03-12	10 mi
Registration #2	2016-02-29	128.294 mi
Registration #3	2017-02-17	138.019 mi
Registration #4	2017-02-17	138.019 mi
Registration #5	2018-03-09	145.910 mi
Registration #6	2018-03-09	145.910 mi
Registration #7	2019-03-14	152.564 mi
Registration #8		11.117 esi
Registration #9		11.117 esi
Registration #10		11.777 esi
Registration #11		11.117 esi
Registration #12		11.777 est
Registration #13		11.117 esi

More info \rightarrow





Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
50566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight	
Width	2097 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1602 kg
Max. allowed weight	2130 kg
Additional information	
Fuel tank capacity	67 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12