





report date: 2024-03-29

General information

Make	ABARTH
Model	500 ABARTH
Colour	White
Year of manufacture	2010
Top speed	129 mph
0 - 60 mph	7.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	135 BHP
Max. torque	180 Nm at 2.500 rpm
Engine capacity	1.368 сс
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	43.5 mpg
CO2 emission	155 g/km
CO2 label	G



CarCheck.co.uk page 1/12



MOT history

MOT expiry date	2024-12-19
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	15
Total items failed	16

MOT #15	2023-12-20 16:25
MOT test number	828356187211
Result	✓ Passed
Next expiry date	2024-12-19
Advice Nearside Front Play in steering rack inner joint(s)	

MOT #14		2023-12-08 17:15
MOT test	number	690429484837
Result		≍ Failed
Fail N	learside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))		
	learside Front Inner Drive shaft joint constant velocity boot split or insecure, dirt $(6.1.7 (g) (ii))$	no longer prevents the
Fail O	offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail E	xhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))	
Advice	Nearside Front Play in steering rack inner joint(s)	
Fail N	learside Rear Position lamp not working (4.2.1 (a) (ii))	

CarCheck.co.uk page 2/12



MOT #13 2022-12-01 17:06

MOT test number 819419845539

Advice Rear axle beam corroded

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12 2021-12-18 13:50

MOT test number 265811138351

Result ✓ Passed

Advice (Rear axle slight corrosion)

MOT #11 2021-12-09 17:08

MOT test number 148722493695

Result X Failed

Fail Exhaust has a major leak of exhaust gases (6.1.2 (a))

Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice (Rear axle slight corrosion)

Fail Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Emissions not tested (8.2.1.2 (d))

Fail Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #10 2020-11-05 16:16

MOT test number 443988884611

CarCheck.co.uk page 3/12



MOT #9 2020-10-27 10:04

MOT test number 966774170016

Result X Failed

Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Fail Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))

Fail Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

MOT #8 2020-01-11 07:54

MOT test number 147387585158

Result ✓ Passed

MOT #7 2018-12-13 14:23

MOT test number 593250419228

Result

Passed

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2017-12-29 11:33

MOT test number 674314888023

Result ✓ Passed

CarCheck.co.uk page 4/12



MOT #5

MOT test number

621716638000

Result

✓ Passed

Advice Offside Rear Shock absorber has a slightly worn bush (2.7.4)

Advice Front brake discs slightly corroded on inside face

MOT #4

MOT test number

Result

Advice Front tyres perished on the outer side walls

Advice Rear wiper torn

MOT #3

MOT test number

985863232503

Result

✓ Passed

MOT #2 2015-01-17 09:01

MOT test number 508377015068

Result ✓ Passed

MOT #1 2014-01-11 09:16

MOT test number 119141914478

Result ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check

Tax expired: 27 April 2024





Expires: 19 December 2024

Tax status

Days left

MOT expiry date

Full MOT history

Expired at 27 April 2024

3 days too late

19 December 2024

See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



DS60JNV

report date: 2024-03-29

Damage history

Check the damage history for this ABARTH. See if, where and when this ABARTH had damage and the car repair costs. We also check if this ABARTH was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra ABARTH salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this ABARTH in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when miscory	
For how long did the current and previous owner(s) have this ABARTH? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
manus .	
	More info >
Plate changes	
See in this check if this ABARTH had different number plates.	
Number of plates	,
Current registration	IK SIE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this ABARTH is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this ABARTH has been settled.

If not, and you buy this ABARTH then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this ABARTH is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-12-31
Last registration	2023-12-20
Complete history	See info



Registration #1	2010-12-31	28 mi
Registration #2	2014-01-11	5.929 mi
Registration #3	2015-01-17	6.260 mi
Registration #4	2015-12-29	6.659 mi
Registration #5	2017-02-01	13.935 mi
Registration #6	2017-07-17	17.404 mi
Registration #7	2017-12-29	18.901 mi
Registration #8	2018-12-13	29.206 mi
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 es
Registration #12		11.177 es
Registration #13		91.077 mi
Registration #14		0.00 44
Registration #15		11.777 mi

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 11/12



		_		
I) I m	ancian	C).	weight	-
	CHSIUL	3 W	weiuii	L

Width	1627 mm
Height	1488 mm
Length	3657 mm
Wheel base	2300 mm
Kerb weight	1035 kg
Max. allowed weight	1425 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	1491003

CarCheck.co.uk page 12/12