



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA LIFE 16V
Colour	Silver
Year of manufacture	2005
Top speed	126 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	166 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.2 mpg
Consumption extra urban	51.4 mpg
Consumption combined	38.7 mpg
CO2 emission	175 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-07-30
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2023-05-17
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	32
Total items failed	12

MOT #19	2022-05-18 10:50
MOT test number	167395045970
Result	✓ Passed
Next expiry date	2023-05-17
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Rear Exhaust mounting defective system fouling on rear subframe were repair been made (6.1.2 (a))

**MOT #18**

2022-05-16 10:40

MOT test number

308422433711

Result**✗ Failed****Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**Fail** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Anti-lock braking system wiring excessively damaged fouling on wheel (1.6 (d))**Advice** Rear Exhaust mounting defective system fouling on rear subframe were repair been made (6.1.2 (a))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**MOT #17**

2021-05-15 15:11

MOT test number

489583528530

Result**✓ Passed****MOT #16**

2021-05-08 13:16

MOT test number

376486464330

Result**✗ Failed****Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #15** 2020-05-09 11:03**MOT test number** 802705668402**Result** ✓ Passed

Advice Brake pipe corroded, covered in grease or other material both front to rears metal brake pipes (1.1.11 (c))

MOT #14 2019-02-23 15:14**MOT test number** 358282213817**Result** ✓ Passed

Advice Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

Advice Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

MOT #13 2018-02-17 10:01**MOT test number** 269062672945**Result** ✓ Passed

Advice Signs of coolant leak from water pump area, further investigation required

Advice Offside Rear brake pipe corroded, strongly advise replacement

MOT #12 2017-03-04 12:49**MOT test number** 630701867255**Result** ✓ Passed

Advice Offside Drive shaft oil seal leaking

Advice Offside Brake pipe slightly corroded Front to rear (3.6.B.2c)

MOT #11 2016-03-04 12:16**MOT test number** 757080759510**Result** ✓ Passed

Advice O/S/F Coil spring has piece missing on bottom but is sitting correctly.

Advice Brake pipe slightly corroded Front to rear brake pipes corroding (3.6.B.2c)

**MOT #10**

2015-03-13 11:44

MOT test number

338842275008

Result

✓ Passed

Notice Oil leak**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Rear wash not working**Advice** Nearside Front Tie bar/rod ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**MOT #9**

2015-03-09 11:06

MOT test number

689458765024

Result

✗ Failed

Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Oil leak**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**Advice** Nearside Front Tie bar/rod ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Notice** Rear wash not working**MOT #8**

2014-03-10 10:38

MOT test number

127119564404

Result

✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Inner Front Track rod end ball joint has slight play (2.2.B.1f)**Notice** Oil leak**Advice** Nearside Front Lower Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

**MOT #7** 2013-03-11 13:31**MOT test number** 486070273078**Result** ✓ Passed**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**MOT #6** 2013-03-08 14:24**MOT test number** 115037163436**Result** ✗ Failed**Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**Fail** Offside Rear coil spring incomplete (2.4.C.1a)**MOT #5** 2012-03-08 11:32**MOT test number** 767408262046**Result** ✓ Passed**MOT #4** 2011-01-10 14:45**MOT test number** 555780011060**Result** ✓ Passed**Advice** Offside Front Lower Tie bar/rod has slight play in a ball joint (2.4.G.2)**MOT #3** 2010-01-12 13:16**MOT test number** 524562410085**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)



MOT #2	2009-01-09 11:38
MOT test number	584539609065
Result	✓ Passed

MOT #1	2008-01-08 10:52
MOT test number	651348408050
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
29 January 2024

✕
MOT

Expired:
17 May 2023

Tax status	Expired at 29 January 2024
Days left	91 days too late
MOT expiry date	17 May 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 KH54WXX
Plate since	2019-06-29
Current registration	 KH54WXX
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-01-09
Last registration	2022-05-18
Complete history	See info



Registration #1	2005-01-09	7 mi
Registration #2	2008-01-08	26.350 mi
Registration #3	2009-01-09	30.470 mi
Registration #4	2010-01-12	34.846 mi
Registration #5	2011-01-10	40.731 mi
Registration #6	2012-03-08	44.727 mi
Registration #7	2013-03-08	51.738 mi
Registration #8	2013-03-11	51.855 mi
Registration #9	2014-03-10	57.408 mi
Registration #10	2015-03-09	64.544 mi
Registration #11	2015-03-13	64.570 mi
Registration #12	2016-05-20	65.000 mi
Registration #13	2016-05-20	65.000 mi
Registration #14	2016-05-20	65.000 mi
Registration #15	2016-05-20	65.000 mi
Registration #16	2016-05-20	65.000 mi
Registration #17	2016-05-20	65.000 mi
Registration #18	2016-05-20	65.000 mi
Registration #19	2016-05-20	65.000 mi
Registration #20	2016-05-20	65.000 mi
Registration #21	2016-05-20	65.000 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4596 mm
Wheel base	2700 mm
Kerb weight	1379 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	20EH1573