





General information

Make	ΤΟΥΟΤΑ
Model	COROLLA VVTI T SPIRIT
Colour	Silver
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.8 mpg
Consumption combined	40.3 mpg





Internet history

Entry 2	
Date	2021-07-01
Pictures	21
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-06-30
Pictures	0
Listing price	<u>View report</u>

source: autotrader.co.uk



MOT history

MOT #17	2022-07-16 12:25
MOT test number	855117640360
Result	✓ Passed
Next expiry date	2023-07-19
Advice Front Suspension arm pin or bush worn but not resulting in excessive move	ement (5.3.4 (a) (i))
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Front Headlamp lens slightly defective both side (4.1.1 (b) (i))	
Advice Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteri	orated (6.1.7 (g) (i))

MOT #16 2022-07-16 12:25 **MOT test number** 607185337022 Result × Failed Minor Front Headlamp lens slightly defective both side (4.1.1 (b) (i)) Pass with rectification Offside Front Headlamp aim too low (4.1.2 (a)) Advice Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) Advice Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #15	2021-06-29 17:06
MOT test number	576618670028
Result	✓ Passed
Advice Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))Advice Rear axle bushes perishing bothsides	



MOT #14	2021-06-28 17:14
MOT test number	855072125739
Result	🗙 Failed
Fail Front Brakes imbalanced across an axle (1.2.1 (b) (i))	
Advice Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Rear axle bushes perishing bothsides	
Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	

MOT #13	2020-07-20 15:23
MOT test number	599729159330
Result	✓ Passed

MOT #3	12	2020-07-17 13:48
MOT te	st number	556751902411
Result		🗙 Failed
Fail	Brake pedal has insufficient reserve travel (1.1.2 (a))	
Fail	Nearside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #11	2019-07-19 14:29
MOT test number	278975889199
Result	✓ Passed
NOT #10	

MO1 #10	2018-07-23 10:17
MOT test number	282161844154
Result	✓ Passed

МОТ #9	2017-07-13 10:20
MOT test number	711399022552
Result	✓ Passed

EN06PDK

report date: 2024-03-29





MOT #8	2016-07-08 11:29
MOT test number	138073406682
Result	✓ Passed
Advice Nearside Rear tyre wall is cracked	
MOT #7	2015-07-15 11:27
MOT test number	567566795149
Result	✓ Passed
MOT #6	2014-07-21 09:05
MOT test number	697902004209
Result	✓ Passed
Notice Nearside rear tyre wall cracking	
MOT #5	2013-07-15 10:48
MOT test number	789036893171
Result	✓ Passed
МОТ #4	2012-07-20 09:42
MOT test number	818492802264
Result	✓ Passed
MOT #3	2011-07-16 11:45
MOT test number	647097391172
Result	✓ Passed
MOT #2	2010-07-23 10:40
MOT test number	923704200245
Result	✓ Passed
Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)	





🗸 Passed

MOT #1	2009-07-14 09:42
MOT test number	491985599164

Result





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	 Lamp
Туре	K K K K K K K K K K K K K K K K K K K
Damage 2	AMPLE
Damage 2	e et a
Date	 *
Category	 amer
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this TOYOTA had different number plate	es.
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow



ENO6PDK report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-07-25
Last registration	2022-07-16
Complete history	See info



2006-07-25	26 mi
2009-07-14	29.827 mi
2010-07-23	39.455 mi
2011-07-16	47.701 mi
2012-07-20	57.895 mi
2013-07-15	66.241 mi
2014-07-21	73.785 mi
2015-07-15	77.460 mi
2016-07-08	81.203 mi
2017-07-13	85.266 mi
2017-07-13	85.266 mi
	2009-07-14 2010-07-23 2011-07-16 2012-07-20 2013-07-15 2014-07-21 2015-07-15







Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1220 kg
Max. allowed weight	1655 kg
Additional information	
Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	3ZZU778649