





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF GT TDI DSG
Colour	Silver
Year of manufacture	2010
Top speed	129 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	140 BHP	
Max. torque	320 Nm at 1.750 rpm	
Engine capacity	1.968 cc	
Cylinders	4	
Fuel type	Diesel	
Consumption city	39.8 mpg	
Consumption extra urban	62.8 mpg	
Consumption combined	52.3 mpg	
CO2 emission	138 g/km	
CO2 label	E	



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-06-14

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-02-27
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	14
Total items failed	4

MOT #14	2023-02-02 12:06
MOT test number	822826909752
Result	✓ Passed
Next expiry date	2024-02-27

MOT #13	2022-02	-28 14:45
MOT test	number 85848	88903517
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Advice	Offside side repeater light intensity slightly reduced	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii	i))

CarCheck.co.uk page 3/13



MOT #12 2022-02-28 10:04

MOT test number 966739458106

Result X Failed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside side repeater light intensity slightly reduced

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Nearside Side repeater light intensity significantly reduced (4.4.3 (a))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11 2021-01-26 16:29

MOT test number 638801546906

MOT #10 2020-02-20 08:44

MOT test number 929198755414

Result
✓ Passed

MOT #9 2020-02-19 11:11

MOT test number 525268393108

Result X Failed

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

MOT #8 2019-02-25 14:46

MOT test number 110222941044

CarCheck.co.uk page 4/13



MOT #7 2018-02-20 10:37

MOT test number 797896612977

MOT #6 2017-02-17 10:20

MOT test number 761610520299

Result ✓ Passed

MOT #5 2017-02-15 13:42

MOT test number 524222388279

Result X Failed

Fail Front registration plate obscured (6.3.1d)

Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #4 2016-02-25 14:05

MOT test number 793750011085

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #3 2015-04-24 13:50

MOT test number 609454815112

Result
✓ Passed

Notice Items removed from driver's view prior to test

Notice Nearside rear brake pads wearing thin

MOT #2 2014-04-28 09:46

MOT test number 468428914158

Result
✓ Passed

CarCheck.co.uk page 5/13



MOT #1 2013-03-15 17:05

MOT test number 128174173059

Result ✓ Passed

CarCheck.co.uk page 6/13





Tax & MOT check



X MOT

Tax expired: 1 January 2024 Expired: 27 February 2024

Tax status	Expired at 1 January 2024
Days left	120 days too late
MOT expiry date	27 February 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.


Damage 1

Date	
Category	
Туре	
Damage 2	

Date

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NIE
Plate since	
Current registration	NK NE
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-04-07
Last registration	2023-02-02
Complete history	See info



Registration #1	2010-04-07	17 mi
Registration #2	2013-03-15	29.081 mi
Registration #3	2014-04-28	36.372 mi
Registration #4	2015-04-24	44.135 mi
Registration #5	2016-02-25	52.172 mi
Registration #6	2017-02-15	59.966 mi
Registration #7	2017-02-17	59.975 mi
Registration #8	2018-02-20	67.159 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

PRIN. PR. PR

More info >

77. 777 mg

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1322 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack co.uk	nago 12/13

CarCheck.co.uk page 13/13

Number of seats	5
Number of axles	2
Engine number	CFF 128191