



report date: 2024-03-28

General information

Make	FIAT
Model	500C POP
Colour	Pink
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 6.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-03-16
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	66
Total items failed	10

MOT #19	2024-03-13 10:31
MOT test number	685983805433
Result	✓ Passed
Next expiry date	2025-03-16
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Rear Exhaust outer skin corroded
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #18**

2024-03-13 10:31

MOT test number

846329544526

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Rear Exhaust outer skin corroded
- Advice** Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #17

2023-02-24 13:39

MOT test number

881119948007

Result**✓ Passed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases front and rear exhaust corroded (6.1.2 (a))
- Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #16

2022-03-09 08:08

MOT test number

329425018068

Result**✓ Passed**

- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Exhaust corroded
- Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

**MOT #15** 2022-03-09 08:08**MOT test number** 654475409679**Result** ✗ Failed**Advice** Exhaust corroded**Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Pass with rectification** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #14** 2021-03-17 14:14**MOT test number** 531123302804**Result** ✓ Passed**MOT #13** 2021-03-16 16:41**MOT test number** 408009060489**Result** ✗ Failed**Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #12** 2020-09-01 17:07**MOT test number** 453154601669**Result** ✗ Failed**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

**MOT #11**

2019-10-17 11:26

MOT test number

147121533001

Result

✓ Passed

- Advice** Offside Front Top mount has slight play
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Exhaust corroded
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Central Brake light inoperative

MOT #10

2018-10-24 11:06

MOT test number

148962172347

Result

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Sump corroded
- Advice** Exhaust system corroded

MOT #9

2018-10-17 12:47

MOT test number

138352310178

Result

✗ Failed

- Advice** Exhaust system corroded
- Advice** Nearside Front Lower arm bush worn
- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Sump corroded
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #8**

2017-10-18 12:30

MOT test number

381403942189

Result

✓ Passed

- Advice** Oil leak
- Advice** NSR tyre losing shape
- Advice** Slight corrosion underneath to components and chassis/body
- Advice** Centre exhaust clamp missing
- Advice** Rear shock bushes perished
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Exhaust corroded
- Advice** Centre brake light inop

MOT #7

2017-10-13 12:08

MOT test number

511543821776

Result

✗ Failed

- Advice** Centre exhaust clamp missing
- Advice** Exhaust corroded
- Advice** Centre brake light inop
- Advice** Oil leak
- Fail** Offside Front Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)
- Advice** NSR tyre losing shape
- Advice** Slight corrosion underneath to components and chassis/body
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Rear shock bushes perished

**MOT #6**

2017-10-12 10:02

MOT test number

863715012647

Result**✗ Failed**

- Advice** Upper Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)
- Advice** Rear exhaust outer skin corroded
- Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Nearside Rear Shock absorber has an excessively worn bush (2.7.4)
- Advice** Coolant level low
- Advice** Oil leak
- Advice** Exhaust clamp missing from join on middle/rear
- Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Advice** Rear coil spring corroded (2.4.C.1b)
- Advice** Oil level on min

MOT #5

2016-10-04 14:18

MOT test number

765085283187

Result**✓ Passed**

- Advice** Centre /?middle clamp missing
- Advice** Rear exhaust corroded/outer skin vanished slight leak

MOT #4

2015-10-10 10:46

MOT test number

567161730943

Result**✓ Passed**

- Advice** Nearside Rear Upper Shock absorber has a slightly worn bush (2.7.4)



MOT #3	2014-09-20 14:45
MOT test number	385403564215
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2013-10-19 10:01
MOT test number	169192093275
Result	✓ Passed
Notice	Nail in nearside front tyre
Notice	Both front tyres wearing inner edges

MOT #1	2013-05-08 14:17
MOT test number	637548623101
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
16 March 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	16 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	KN60ZTR
Plate since	2019-09-28
Current registration	KN60ZTR
Plate since	2019-09-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2010-11-02
Last registration	2024-03-13
Complete history	See info



Registration #1	2010-11-02	24 mi
Registration #2	2013-05-08	14.647 mi
Registration #3	2013-10-19	18.532 mi
Registration #4	2014-09-20	25.912 mi
Registration #5	2015-10-10	37.576 mi
Registration #6	2016-10-04	47.645 mi
Registration #7	2017-10-12	58.216 mi
Registration #8	2017-10-13	58.240 mi
Registration #9	2017-10-18	58.260 mi
Registration #10	2018-10-17	66.275 mi
Registration #11	2018-10-24	66.295 mi
Registration #12	2019-10-20	74.310 mi
Registration #13	2019-10-27	82.325 mi
Registration #14	2019-11-03	90.340 mi
Registration #15	2019-11-10	98.355 mi
Registration #16	2019-11-17	106.370 mi
Registration #17	2019-11-24	114.385 mi
Registration #18	2019-12-01	122.400 mi
Registration #19	2019-12-08	130.415 mi
Registration #20	2019-12-15	138.430 mi
Registration #21	2019-12-22	146.445 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	5582676