




report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 PURETECH DSIGN ICE
Colour	Blue
Year of manufacture	2015
Top speed	108 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	80 BHP
Max. torque	118 Nm at 2.750 rpm
Engine capacity	1.199 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	107 g/km
CO2 label	B





Internet history

Entry 2

Date	2023-10-26
Pictures	7
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-10-22
Pictures	6
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-14
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	33
Total items failed	8

MOT #8	2023-09-15 05:37
MOT test number	206236508828
Result	✓ Passed
Next expiry date	2024-09-14
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #7** 2023-08-23 08:14**MOT test number** 953254590000**Result** ✗ Failed**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Service brake binding but not excessively ****borderline**** (1.2.1 (f))**Advice** Cooling fan never cut in possible fault**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Rear axle corroded**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #6** 2021-10-30 09:45**MOT test number** 242408404657**Result** ✓ Passed**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Front Exhaust has a minor leak of exhaust gases central (6.1.2 (a))**MOT #5** 2020-11-16 11:49**MOT test number** 746004037991**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Service light on**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #4**

2020-11-16 09:21

MOT test number

474924068080

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Service light on
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #3

2019-05-14 07:05

MOT test number

387565770677

Result**✓ Passed**

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing badly unevenly worn flat spots on tread 1.6mm (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 1.6mm on limit (5.2.3 (e))
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 30% (1.2.1 (b) (i))
- Minor** Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #2**

2019-05-13 14:51

MOT test number

930346472886

Result**✗ Failed**

- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 1.6mm on limit (5.2.3 (e))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 30% (1.2.1 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing badly unevenly worn flat spots on tread 1.6mm (5.2.3 (d) (ii))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Minor** Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))

MOT #1

2018-05-09 08:17

MOT test number

254604544871

Result**✓ Passed**

- Advice** N/s/f tyre down to 3mm
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
14 September 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	14 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-05-22
Last registration	2023-09-15
Complete history	See info



Registration #1	2015-05-22	11 mi
Registration #2	2018-05-09	59.844 mi
Registration #3	2019-05-13	80.585 mi
Registration #4	2019-05-14	80.585 mi
Registration #5	2020-11-16	100.417 mi
Registration #6	2020-11-16	100.419 mi
Registration #7	2020-11-16	100.419 mi
Registration #8	2020-11-16	100.419 mi
Registration #9	2020-11-16	100.419 mi
Registration #10	2020-11-16	100.419 mi
Registration #11	2020-11-16	100.419 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1708 mm
Height	1460 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	975 kg
Max. allowed weight	1496 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	B2080368694