





General information

| Make | CITROEN |
|---------------------|---------------------------------|
| Model | C4 PICASSO BLUEHDI PLATINUM S/S |
| Colour | Grey |
| Year of manufacture | 2018 |
| Top speed | 122 mph |
| 0 - 60 mph | 10.6 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 118 BHP |
|-------------------------|---------------------|
| Max. torque | 300 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 64.2 mpg |
| Consumption extra urban | 80.7 mpg |
| Consumption combined | 74.3 mpg |
| CO2 emission | 100 g/km |
| CO2 label | A |







| Internet history | | |
|-------------------------------------------------|----------------------------------|--|
| Entry 3 | | |
| Date | 2021-06-29 | |
| Pictures | 50 | |
| Listing price | View report | |
| Free Professional Valuation $\widehat{\}$ | Minimum 12 Months Warranty | |
| Entry 2 | | |
| Date | 2021-06-08 | |
| Pictures | 52 | |
| Listing price | View report | |
| AUB HYA | Minimum 12 Months Warranty | |
| source: yesauto.com | | |
| Entry 1 | | |
| Date | 2021-06-08 | |
| Pictures | 10 | |
| Listing price | View report | |
| | | |









source: autoonline.co.uk



MOT history

| MOT expiry date | 2025-03-07 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 4 |
| Failed MOT tests | 1 |
| Total advice items | 4 |
| Total items failed | 2 |

| MOT #5 | | 2024-02-28 10:48 |
|-----------------------|------------------------------------------------------------------|------------------|
| MOT test number | | 364717114042 |
| Result | | 🗸 Passed |
| Next expiry date | | 2025-03-07 |
| Advice Rear P | assenger seat(s) missing at time of test Rear folded and covered | |
| Advice Nearsi | de Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice Offside | e Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #4 | 2023-02-22 14:19 |
|-----------------|------------------|
| MOT test number | 287004183803 |
| Result | ✓ Passed |

| MOT #3 | 2022-03-03 16:49 |
|------------------------------------------------------------------|-------------------------------------|
| MOT test number | 702055347241 |
| Result | ✓ Passed |
| Advice Rear Brake disc worn, pitted or scored, but not seriously | weakened corroded (1.1.14 (a) (ii)) |

| MOT #2 | 2021-02-25 16:02 |
|-----------------|------------------|
| MOT test number | 210471504181 |
| Result | ✓ Passed |





| MOT # | 1 | 2021-02-25 14:07 |
|--------|----------------------------------------------------------------------------------|------------------|
| MOT te | est number | 971542008187 |
| Result | | 🗙 Failed |
| Fail | Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) | |
| Fail | Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) | |



Tax & MOT check

| ✓ Taxed | √ МОТ |
|---------------------------|---------------------------------|
| Tax due: 1 August 2024 | Expires: 7 March 2025 |
| Tax status | Valid until 1 August |
| Days left | 94 |
| MOT expiry date | 7 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|------------------------------------------------------|------------|
| Band | E |
| First licence fee (12 months) | £ 165,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 185,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|----------------------------------------|
| Date | FEIDO |
| Category | Lamp |
| Туре | |
| Damage 2 | VAMPL |
| Date | ······································ |
| Category | AMP |
| Туре | |

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| ************ | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this CITROEN had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | More info > |





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 9 |
| First mileage registration | 2018-03-08 |
| Last registration | 2024-02-28 |
| Complete history | <u>See info</u> |



| Registration #1 | 2018-03-08 | 23 mi |
|-----------------|------------|------------|
| Registration #2 | 2021-02-25 | 13.920 mi |
| Registration #3 | 2021-02-25 | 13.920 mi |
| Registration #4 | | 11.777 esi |
| Registration #5 | | 11.227 mi |
| Registration #6 | | 11.777 esi |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 esi |

More info >





Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 90% |
| Children | 85% |
| Pedestrian | 43% |
| Safety systems | 97% |
| Overall rating | 80% |
| Video | see crash video |



| Dimensions & weight | |
|--------------------------------------------------------|--------------------------|
| Width | 1789 mm |
| Height | 1489 mm |
| Length | 4329 mm |
| Wheel base | 2608 mm |
| Kerb weight | 1280 kg |
| Max. allowed weight | 1860 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 60 l |
| | 60 l Direct Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Direct Injection |
| Fuel tank capacity Fuel delivery Number of doors | Direct Injection 5 |