





report date: 2024-03-28

### General information

Make	FORD
Model	FIESTA ZETEC
Colour	Black
Year of manufacture	2018
Top speed	105 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	84 BHP
Max. torque	108 Nm
Engine capacity	1.084 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	76.3 mpg
Consumption combined	64.2 mpg
CO2 emission	101 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-28


## Internet history

#### Entry 2

Date 2021-07-24

Pictures 19

Listing price <u>View report</u>









source: yesauto.com

#### Entry 1

Date	2021-07-18
Pictures	2

Listing price <u>View report</u>





source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

## MOT history

MOT expiry date	2024-10-10
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	15
Total items failed	2

MOT #6	2023-10-11 07:42
MOT test number	754020394055
Result	✓ Passed
Next expiry date	2024-10-10
Advice Undertray damaged	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Items removed from driver's view prior to test	

MOT #5	2023-10-11 07:42
MOT test number	652114801729
Result	<b>×</b> Failed
Advice Items removed from driver's view prior to test	
Pass with rectification Windscreen washer provides insufficient	ent washer liquid (3.5 (a))
Advice Undertray damaged	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

Result

Advice Front Lower Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Upper Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #3** 2022-08-08 08:35 **MOT** test number 972997364424 Result × Failed **Advice** Front Lower Oil leak, but not excessive (8.4.1 (a) (i)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Nearside Rear Nail in tyre Advice Nearside Rear Upper Shock absorbers has light misting of oil (5.3.2 (b)) **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

 MOT #2
 2021-09-03 15:44

 MOT test number
 433346549054

 Result
 ✓ Passed

MOT #1

MOT test number

478742872757

Result

Advice

Tyre slightly damaged/cracking or perishing All 4 tyres slight cracking in tread (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	10 October 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



GY67GSO report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



GY67GSO report date: 2024-03-28

Owner history

e when misterly		
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report		ave?
*********		
***************************************		
***************************************		
	More info	>
Plate changes  See in this check if this FORD had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	NK NA	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-28

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-01-19
Last registration	2023-10-11
Complete history	See info



Registration #1	2018-01-19	8 mi
Registration #2	2021-01-14	7.646 mi
Registration #3		11.777 mi
Registration #4		11.777 es
Registration #5	2021-09-03	9.004 mi
Registration #6		11.777 es
Registration #7		11.777 mi
Registration #8		
		11.111 au

More info >

CarCheck.co.uk page 10/11



GY67GSO report date: 2024-03-28

Car features

50225	Air conditionir
50295	
50482	
60501	
60566	
60567	
50569	

# Safety ratings

NCAP rating	****
Adult	87%
Children	84%
Pedestrian	64%
Safety systems	60%
Overall rating	76%
Video	see crash video



# Dimensions & weight

Width	1978 mm
Height	1495 mm
Length	3969 mm
Wheel base	2489 mm
Kerb weight	1113 kg
Max. allowed weight	1620 kg

### Additional information

Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Engine number Carcheck.co.uk	HR62931 page 11/11