



report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA DESIRE 16V PICASSO E4
Colour	Brown
Year of manufacture	2008
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg
CO2 emission	172 g/km
CO2 label	H








Internet history

Entry 1

Date	2021-06-04
Pictures	38
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-05-03
MOT pass rate	60 %
MOT passed	15
Failed MOT tests	10
Total advice items	18
Total items failed	10

MOT #25	2024-04-08 08:42
MOT test number	927926788909
Result	✓ Passed
Next expiry date	2025-05-03

MOT #24	2024-04-08 08:42
MOT test number	229489487618
Result	✗ Failed
Pass with rectification	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Pass with rectification	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #23	2023-04-18 15:32
MOT test number	728409355128
Result	✓ Passed

MOT #22	2023-04-18 09:11
MOT test number	715988628345
Result	✗ Failed
MAJOR	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

**MOT #21** 2022-04-05 08:53**MOT test number** 166912802292**Result** ✓ Passed**MOT #20** 2022-04-05 08:53**MOT test number** 195528114336**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #19** 2021-05-04 14:42**MOT test number** 242349399108**Result** ✓ Passed**MOT #18** 2021-04-27 14:37**MOT test number** 945640921231**Result** ✓ Passed**MOT #17** 2021-04-16 14:51**MOT test number** 132955805161**Result** ✗ Failed**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Headlamp aim too low (4.1.2 (a))**MOT #16** 2020-10-26 10:37**MOT test number** 894051267857**Result** ✓ Passed**Advice** Nearside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))

**MOT #15** 2019-09-18 10:04**MOT test number** 246785806310**Result** ✓ Passed**MOT #14** 2019-09-18 10:04**MOT test number** 917393341950**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #13** 2018-10-01 13:12**MOT test number** 935163260991**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2018-09-21 14:58**MOT test number** 388905236457**Result** ✗ Failed**MAJOR** Nearside Front Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill panel (7.1.1 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Outer Subframe mounting prescribed area excessively corroded significantly reducing structural strength sill panel (5.3.6 (a) (i))**MOT #11** 2017-09-08 13:44**MOT test number** 363729950286**Result** ✓ Passed**Advice** N/s rear tyre wearing on inner & outer edges

**MOT #10** 2017-09-08 13:43**MOT test number** 993379122074**Result** ✗ Failed**Advice** N/s rear tyre wearing on inner & outer edges**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #9** 2016-09-09 10:03**MOT test number** 372406240163**Result** ✓ Passed**Advice** Rear exhaust box bracket corroded**MOT #8** 2016-09-09 10:03**MOT test number** 728940849672**Result** ✗ Failed**Advice** Rear exhaust box bracket corroded**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**MOT #7** 2015-09-12 10:52**MOT test number** 903460715359**Result** ✓ Passed**MOT #6** 2014-09-12 09:09**MOT test number** 399125354270**Result** ✓ Passed**Notice** Rear exhaust mount bracket heavily corroded**Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #5** 2014-09-12 09:09**MOT test number** 367865454222**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Notice** Child seat fitted not allowing full inspection of adult belt**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Notice** Rear exhaust mount bracket heavily corroded**MOT #4** 2013-09-16 11:26**MOT test number** 157969953204**Result** ✓ Passed**MOT #3** 2012-09-27 09:17**MOT test number** 789651172288**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2011-09-23 12:22**MOT test number** 437676161245**Result** ✓ Passed**MOT #1** 2011-09-23 09:27**MOT test number** 958076661224**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
3 May 2025

Tax status	Valid until 1 June
Days left	32
MOT expiry date	3 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2008-09-19
Last registration	2024-04-08
Complete history	See info



Registration #1	2008-09-19	11 mi
Registration #2	2011-09-23	21.810 mi
Registration #3	2011-09-23	21.810 mi
Registration #4	2012-09-27	30.021 mi
Registration #5	2013-09-16	38.826 mi
Registration #6	2014-09-12	50.805 mi
Registration #7	2015-09-12	53.862 mi
Registration #8	2016-09-09	56.351 mi
Registration #9	2016-09-09	56.351 mi
Registration #10	2017-09-08	58.769 mi
Registration #11	2017-09-08	58.769 mi
Registration #12	2018-09-21	61.796 mi
Registration #13	2018-10-01	61.832 mi
Registration #14	2019-09-01	61.832 mi
Registration #15	2019-09-01	61.832 mi
Registration #16	2019-09-01	61.832 mi
Registration #17	2019-09-01	61.832 mi
Registration #18	2019-09-01	61.832 mi
Registration #19	2019-09-01	61.832 mi
Registration #20	2019-09-01	61.832 mi
Registration #21	2019-09-01	61.832 mi
Registration #22	2019-09-01	61.832 mi
Registration #23	2019-09-01	61.832 mi
Registration #24	2019-09-01	61.832 mi
Registration #25	2019-09-01	61.832 mi
Registration #26	2019-09-01	61.832 mi

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1240 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX7U3371415