



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	VIVA SE AC
Colour	White
Year of manufacture	2016
Top speed	106 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	74 BHP
Max. torque	95 Nm at 4.500 rpm
Engine capacity	999 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	104 g/km
CO2 label	B







Internet history

Entry 1

Date	2021-01-29
Pictures	9
Listing price	<a href="#">View report</a>



source: yesauto.com



## MOT history

MOT expiry date	2024-07-03
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	9
Total items failed	3

MOT #7 2023-07-04 08:49

MOT test number 793466904329

Result ✓ Passed

Next expiry date 2024-07-03

- Advice** Exhaust condition deteriorated at front flexi
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn bushes starting to split (5.1.2 (b) (i))
- Advice** Side repeater slightly discoloured both (4.4.3 (a))
- Advice** Front Exhaust mounting defective at flexi mount missing (6.1.2 (a))
- Minor** Offside Windscreen damaged but not adversely affecting driver's view chip (3.2 (a) (i))

MOT #6 2022-08-31 07:30

MOT test number 185287868861

Result ✓ Passed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #5 2022-01-05 09:55

MOT test number 239371940392

Result ✓ Passed

**MOT #4** 2021-01-29 11:11**MOT test number** 992737385247**Result** ✓ Passed**MOT #3** 2021-01-21 08:29**MOT test number** 801370564372**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Front Tyre has ply or cords exposed on outer wall (5.2.3 (d) (ii))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #2** 2020-09-21 16:20**MOT test number** 778475876928**Result** ✓ Passed**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #1** 2019-09-04 11:19**MOT test number** 769734177188**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
3 July 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	3 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 SV66UYJ
Plate since	2019-03-29
Current registration	 SV66UYJ
Plate since	2019-03-29

More info >





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-09-15
Last registration	2023-07-04
Complete history	<a href="#">See info</a>



Registration #1	2016-09-15	12 mi
Registration #2	2019-09-04	7.248 mi
Registration #3	2020-09-21	9.923 mi
Registration #4	2021-01-21	10.692 mi
Registration #5	2021-01-29	10.692 mi
Registration #6	2022-05-20	25,277 mi
Registration #7	2022-05-20	25,277 mi
Registration #8	2022-05-20	25,277 mi
Registration #9	2023-07-04	25,277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1876 mm
Height	1485 mm
Length	3675 mm
Wheel base	2385 mm
Kerb weight	864 kg
Max. allowed weight	1353 kg

Additional information

Fuel tank capacity	32 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	L5Q 162040084L5Q