



report date: 2024-03-28

General information

Make	LAND ROVER
Model	DEFENDER TD HARD TOP
Colour	Red
Year of manufacture	2011
Top speed	82 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	360 Nm at 2.000 rpm
Engine capacity	2.402 cc
Cylinders	4
Fuel type	Diesel
Consumption city	22.6 mpg
Consumption extra urban	32.8 mpg
Consumption combined	28.3 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2022-07-31
Pictures	15
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-10-12
Pictures	22
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-18
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	16
Total items failed	7

MOT #16	2024-04-19 16:37
MOT test number	837814101078
Result	✓ Passed
Next expiry date	2025-04-18

MOT #15	2023-04-14 10:50
MOT test number	654052857084
Result	✓ Passed

MOT #14	2023-04-11 13:33
MOT test number	754319142543
Result	✗ Failed
MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))	
MAJOR Service brake efficiency below requirements (1.2.2 (a) (i))	
MAJOR Offside Front Headlamp aim too high (4.1.2 (a))	

MOT #13	2022-08-02 10:07
MOT test number	124539568814
Result	✓ Passed

**MOT #12** 2021-05-12 15:26**MOT test number** 448753456244**Result** ✓ Passed**MOT #11** 2021-05-05 09:05**MOT test number** 933186145314**Result** ✗ Failed

- DANGEROUS** Rear Tyre tread depth below requirements of 1.6mm Both sides (5.2.3 (e))
- MAJOR** Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
- MAJOR** Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))
- MAJOR** Windscreen wiper not working (3.4 (a))
- MAJOR** Rear fog lamp lens defective such that emitted light is adversely affected lense broken (4.5.1 (b) (ii))

MOT #10 2020-03-26 11:01**MOT test number** 740436545741**Result** ✓ Passed**MOT #9** 2020-03-16 18:31**MOT test number** 810007001548**Result** ✗ Failed

- MAJOR** Rear fog lamp lens defective such that emitted light is adversely affected (4.5.1 (b) (ii))
- MAJOR** Nearside Front Position lamp missing (4.2.1 (a) (ii))

MOT #8 2019-02-19 09:35**MOT test number** 257867210286**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2018-02-13 09:19**MOT test number** 450367333394**Result** ✓ Passed**Advice** Nearside Rear tyre has cut on side wall but cords not exposed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #6** 2018-02-13 09:19**MOT test number** 436038646305**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Headlamp aim too high (1.8)**Advice** Nearside Rear tyre has cut on side wall but cords not exposed**MOT #5** 2017-02-13 10:48**MOT test number** 148874582155**Result** ✓ Passed**MOT #4** 2017-02-06 16:09**MOT test number** 638013076585**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Rear Shock absorber has an excessively worn bush (2.7.4)**Fail** Offside Front wheel bearing rough when rotated (2.5.A.2)**Fail** Registration plate lamp insecure (1.1.C.1c)**Fail** Nearside Panhard rod rubber bush deteriorated resulting in excessive movement (2.4.G.2)



MOT #3	2016-02-02 09:14
MOT test number	490474352149
Result	✓ Passed
MOT #2	2015-01-28 16:32
MOT test number	446848025003
Result	✓ Passed
MOT #1	2014-02-10 16:44
MOT test number	196161844008
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
18 April 2025

Tax status	Valid until 1 April
------------	---------------------

Days left	337
-----------	-----

MOT expiry date	18 April 2025
-----------------	---------------

Full MOT history	See MOT history
------------------	---------------------------------



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	PN11CGV
Plate since	2024-03-28
Current registration	PN11CGV
Plate since	2024-03-28

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-03-01
Last registration	2024-04-19
Complete history	See info



Registration #1	2011-03-01	21 mi
Registration #2	2014-02-10	55.773 mi
Registration #3	2015-01-28	78.296 mi
Registration #4	2016-02-02	95.874 mi
Registration #5	2017-02-06	107.291 mi
Registration #6	2017-02-13	107.291 mi
Registration #7	2018-02-13	116.511 mi
Registration #8	2018-02-13	116.511 mi
Registration #9	2019-02-19	121.197 mi
Registration #10	2020-03-16	121.911 mi
Registration #11	2020-03-16	121.911 mi
Registration #12	2020-03-16	121.911 mi
Registration #13	2020-03-16	121.911 mi
Registration #14	2020-03-16	121.911 mi
Registration #15	2020-03-16	121.911 mi
Registration #16	2020-03-16	121.911 mi
Registration #17	2020-03-16	121.911 mi
Registration #18	2020-03-16	121.911 mi
Registration #19	2020-03-16	121.911 mi

More info >



Dimensions & weight

Width	1790 mm
Height	2128 mm
Length	4040 mm
Kerb weight	1759 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Number of axles	2
Engine number	110819211015244DT