





report date: 2024-03-29

### General information

Make	BMW
Model	525 525D SE
Colour	Silver
Year of manufacture	-
Top speed	141 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed automatic

### Engine & fuel consumption

Power	177 BHP
Max. torque	400 Nm at 2.000 rpm
Cylinders	6
Fuel type	Diesel
Consumption city	26.6 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.2 mpg



CarCheck.co.uk page 1/12



report date: 2024-03-29

# Internet history

_				_	-
-	n	т	rv	,	

End y 1	
Date	2021-09-11
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

### **MOT** history

MOT #19	2021-09-24 08:39
---------	------------------

**MOT test number** 972698097205

**Result** ✓ Passed

Next expiry date 2022-09-23

**MOT #18** 2020-11-27 14:32

**MOT test number** 778325953490

Result \sqrt{Passed}

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #17** 2019-04-23 12:36

**MOT test number** 763848387206

Result \rightarrow Passed

Advice Covers fitted to underside of vehicle not allowing for full inspection

MOT #16 2019-04-23 10:29

**MOT test number** 827976284814

**Result** X Failed

**Advice** Covers fitted to underside of vehicle not allowing for full inspection

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**MOT #15** 2017-08-15 10:42

**MOT test number** 626538303826

**Result** 
✓ Passed

**Advice** Nearside Rear Tyre starting to crack

**Advice** Nearside Front Tyre starting to crack

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #14 2016-08-20 08:55

MOT test number 406623995538

**Result** ✓ Passed

**Advice** Offside Front Upper Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

MOT #13 2016-08-20 08:55

**MOT test number** 781724174588

**Result** X Failed

**Pass with rectification** Nearside Front Steering rack gaiter insecure (2.2.D.2d)

**Advice** Offside Front Upper Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

MOT #12 2015-07-25 08:01

MOT test number 957665528566

Result 

Passed

**MOT #11** 2014-08-09 10:29

MOT test number 277801024232

Result 

Passed

**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)

**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)

**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)

**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)

**MOT #10** 2013-08-20 10:07

**MOT test number** 526322433213

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #9	2012-08-14 16:50
MOT test number	887047922285
Result	<b>✓</b> Passed
Notice Under-trays fitted obscuring some underside components	

Notice Under-trays fitted obscuring some underside components	
MOT #8	2011-08-20 12:17
MOT test number	499132431275
Result	✓ Passed
MOT #7	2010-07-27 14:32
MOT test number	414408300280
Result	✓ Passed
MOT #6	2009-08-24 16:48
MOT test number	613326839296
Result	✓ Passed
MOT #5	2009-04-01 10:53
MOT test number	830741999051
Result	✓ Passed
MOT #4	2008-03-12 10:39
MOT test number	702162078023
Result	<b>✓</b> Passed
Advice Tyre worn close to the legal limit (4.1.E.1)	

MOT #3	2007-03-28 11:25
MOT test number	864487387096
Result	/ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

MOT #2 2006-04-07 12:13 **MOT test number** 221397796079 ✓ Passed Result MOT #1 2006-04-07 11:56 880127796044 **MOT test number** × Failed Result Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage	-
D	
Date	

Category

**Type** 

Damage 2

**Date** 

Category

**Type** 



### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



faste since

**GV04AMK** 

report date: 2024-03-29

More info >

# Owner history For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this BMW had different number plates. ober of plates

CarCheck.co.uk page 9/12



report date: 2024-03-29

### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2004-03-30
Last registration	2021-09-24
Complete history	See info



Registration #1	2004-03-30	14 mi
Registration #2	2006-04-07	32.851 mi
Registration #3	2006-04-07	32.851 mi
Registration #4	2007-03-28	40.411 mi
Registration #5	2008-03-12	49.541 mi
Registration #6	2009-04-01	59.058 mi
Registration #7	2009-08-24	63.088 mi
Registration #8	2010-07-27	70.178 mi
Registration #9	2011-08-20	75.932 mi
Registration #10	2012-08-14	80.519 mi
Registration #11	2013-08-20	88.026 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		D.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

### Car features

50225	Air conditioning
50295	
50482	
60501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1846 mm
Height	1469 mm
Length	4841 mm
Wheel base	2888 mm
Kerb weight	1685 kg
Max. allowed weight	2155 kg

# Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 12/1