





report date: 2024-03-28

#### General information

Make	RENAULT
Model	MEGANE DYNAMIQUE TOMTOM ENERGY DCI S/S
Colour	Black
Year of manufacture	2014
Top speed	118 mph
0 - 100 km/h	12.1 seconds
0 - 60 mph	12.1 seconds
Gearbox	6 speed Manual

#### Engine & fuel consumption

Power	81 kW / 110 HP / 110 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	72.4 mpg
Consumption extra urban	88.3 mpg
Consumption combined	80.7 mpg
CO2 emission	90 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-28

#### Internet history

#### Entry 2

Date 2021-10-02

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1


 Date
 2021-10-01

 Pictures
 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

B 4	$\sim$ $-$		
10.71	$\alpha$	hic:	tory
101	C) I	1115	I U I V
	•		,

MOT expiry date	2024-10-17
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	18
Total items failed	6

MOT #9	2023-10-14 13:38
MOT test number	166944325666
Result	✓ Passed
Next expiry date	2024-10-17

MOT #8	2022-10-13 10:01
MOT test number	366349185609
Result	<b>✓</b> Passed

MOT #7	2021-10-18 15:42
MOT test number	245524118820
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



**Advice** 

Fail

Fail

**BP63LBO** 

report date: 2024-03-28

**MOT** #6 2021-10-15 15:14 **MOT** test number 114550851631 Result × Failed **Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f)) Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing 11 years old (5.2.3 (d) (ii)) Pass with rectification Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) Fail Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii)) Offside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) Minor

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Windscreen wiper not working (3.4 (a))

MOT #5

MOT test number

719787992696

Result

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #4

MOT test number

Result

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))


Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))


MOT #3	2018-09-25 15:56
MOT test number	626462799483
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28





CarCheck.co.uk page 5/12



BP63LB0 report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 December
Days left	217
MOT expiry date	17 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



furthe scinors

BP63LBO

report date: 2024-03-28

More info >

# Owner history For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this RENAULT had different number plates. about of pliates

CarCheck.co.uk page 9/12



report date: 2024-03-28

#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-01-28
Last registration	2023-10-14
Complete history	See info



2014-01-28	21 mi
2017-01-21	23.996 mi
2017-01-21	23.996 mi
2018-09-25	38.800 mi
2019-09-05	47.346 mi
2020-09-21	56.331 mi
	91,777 esi
	11.777 es
	91,777 esi
	11.777 es
	11.777 es
	2017-01-21 2017-01-21 2018-09-25 2019-09-05

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	83%
Children	78%
Pedestrian	60%
Safety systems	56%
Overall rating	72%
Video	see crash video



# Dimensions & weight

Width	1804 mm
Height	1423 mm
Length	4299 mm
Wheel base	2641 mm
Kerb weight	1215 kg
Max. allowed weight	1813 kg

# Additional information

Fuel tank capacity	60 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pag	je 12/12

Number of axles 2

Engine number D292824