




report date: 2024-03-29

General information

Make	FORD
Model	S-MAX
Colour	Silver
Year of manufacture	2014
Top speed	121 mph
0 - 100 km/h	10.2 seconds
Gearbox	6 speed manual

Engine & fuel consumption

Power	103 kW / 140 HP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	50.0 mpg
Consumption combined	44.4 mpg
CO2 emission	139 g/km
CO2 label	E



Internet history

Entry 2

Date	2021-09-13
Pictures	7
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-12
Pictures	7
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-29
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	10
Total items failed	3

MOT #10	2023-05-15 08:21
MOT test number	815199052723
Result	✓ Passed
Next expiry date	2024-05-29
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #9	2022-05-14 10:50
MOT test number	617839123077
Result	✓ Passed

MOT #8	2022-05-14 09:08
MOT test number	905668095536
Result	✗ Failed
Fail	Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #7 2021-05-21 08:17

MOT test number 146832508766

Result ✓ Passed

MOT #6 2020-05-30 09:32

MOT test number 716363817039

Result ✓ Passed

MOT #5 2020-05-23 09:48

MOT test number 475047465545

Result ✗ Failed

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush partly debonded (5.3.4 (a) (i))

Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Fail Nearside Rear Suspension arm pin or bush likely to become detached trailing arm bush debonded (5.3.4 (a) (ii))

MOT #4 2019-05-10 12:20

MOT test number 574447633636

Result ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge 215/60R16 (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 215/60R16 (5.2.3 (e))

MOT #3 2018-05-05 08:01

MOT test number 915711284987

Result ✓ Passed

Advice Unable to test rear seat belts due to seats folded



MOT #2 2017-06-01 20:23

MOT test number 865951398095

Result ✓ Passed

MOT #1 2016-12-19 14:53

MOT test number 323915787555

Result ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 October 2024

✓
MOT

Expires:
29 May 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	29 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-




Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	YX11
Plate since	2019-09-29
Current registration	YX11
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-01-20
Last registration	2023-05-15
Complete history	See info



Registration #1	2014-01-20	22 mi
Registration #2	2016-12-19	27.007 mi
Registration #3	2017-06-01	33.006 mi
Registration #4	2018-05-05	42.424 mi
Registration #5	2019-05-10	55.677 mi
Registration #6	2020-05-23	66.578 mi
Registration #7	2020-05-30	66.735 mi
Registration #8	2020-05-30	66.735 mi
Registration #9	2020-05-30	66.735 mi
Registration #10	2020-05-30	66.735 mi
Registration #11	2020-05-30	66.735 mi
Registration #12	2020-05-30	66.735 mi
Registration #13	2020-05-30	66.735 mi

[More info >](#)



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1590 kg

Additional information

Fuel tank capacity	70 l
Number of axles	2
Engine number	EA09685