



TOYOTA




report date: 2024-03-29

General information

Make	TOYOTA
Model	IQ VVT-I IQ
Colour	Blue
Year of manufacture	2010
Top speed	93 mph
0 - 60 mph	14.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	91 Nm at 4.800 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	57.6 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2022-01-01
Pictures	9
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-10
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	23
Total items failed	6

MOT #12	2023-10-11 12:56
MOT test number	315807525633
Result	✓ Passed
Next expiry date	2024-10-10
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11	2022-11-15 14:08
MOT test number	437374487265
Result	✓ Passed

MOT #10	2021-11-19 15:40
MOT test number	779167600379
Result	✓ Passed
Advice	Rear Brake pipe corroded, covered in grease or other material both side (1.1.11 (c))
Advice	Headlamp has a product on the lens but not seriously reducing light output both side (4.1.4 (b))
Advice	Brake disc worn, pitted or scored, but not seriously weakened front & rear (1.1.14 (a) (ii))
Advice	Front Shock absorbers has light misting of oil both side (5.3.2 (b))
Advice	Both side rear sills slight corroded

**MOT #9**

2021-08-23 13:40

MOT test number

947160959493

Result**✗ Failed**

- Advice** Offside Rear Nail in tyre
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Front Headlamp aim not tested (4.1.2 (b))
- Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))
- Advice** Rear Brake pipe corroded, covered in grease or other material All Pipes. (1.1.11 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Also Cracking And Perishing. (5.2.3 (e))
- Advice** Nearside Front Integral body structure is deformed but structural rigidity is not significantly reduced Front Sill/Jacking Point. (6.1.1 (a) (i))
- Advice** Offside Rear Passenger Seat Head Rest Missing.
- Advice** Items removed from driver's view prior to test
- Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Offside Front Headlamp insecure (4.1.1 (c))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both Sides. (1.1.14 (a) (ii))
- Advice** Rear Brake hose has slight corrosion to ferrule All Hoses. (1.1.12 (f) (i))
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Integral body structure is corroded but structural rigidity is not significantly reduced All Underneath Of Car. (6.1.1 (c) (i))

**MOT #8** 2020-08-20 11:47**MOT test number** 641954641611**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3 mm (5.2.3 (e))
- Advice** Nearside Front bumper slightly insecure but not likely to become de-attached
- Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #7 2019-08-16 10:01**MOT test number** 230670486859**Result** ✓ Passed**MOT #6** 2018-08-20 11:57**MOT test number** 579015039209**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5 2017-08-19 15:25**MOT test number** 825257438552**Result** ✓ Passed**MOT #4** 2016-08-11 12:33**MOT test number** 791461503080**Result** ✓ Passed

- Advice** Offside Rear tyre perished
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #3 2015-07-29 18:18**MOT test number** 818240115231**Result** ✓ Passed



MOT #2	2014-11-27 16:45
MOT test number	978111434392
Result	✓ Passed
MOT #1	2013-11-29 10:26
MOT test number	266553233379
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 February 2025

✓
MOT

Expires:
10 October 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	10 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-11-30
Last registration	2023-10-11
Complete history	See info



Registration #1	2010-11-30	11 mi
Registration #2	2013-11-29	13.596 mi
Registration #3	2014-11-27	18.018 mi
Registration #4	2015-07-29	20.520 mi
Registration #5	2016-08-11	28.904 mi
Registration #6	2017-08-19	37.952 mi
Registration #7	2018-08-20	42.161 mi
Registration #8	2019-08-20	46.370 mi
Registration #9	2020-08-20	50.579 mi
Registration #10	2021-08-20	54.788 mi
Registration #11	2022-08-20	58.997 mi
Registration #12	2023-08-20	63.206 mi
Registration #13	2024-08-20	67.415 mi
Registration #14	2025-08-20	71.624 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	71%
Pedestrian	54%
Safety systems	86%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1680 mm
Height	1500 mm
Length	2985 mm
Wheel base	2000 mm
Kerb weight	845 kg
Max. allowed weight	1215 kg

Additional information

Fuel tank capacity	32 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Engine number	1KR0998678
---------------	------------