



report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE S
Colour	Black
Year of manufacture	2006
Top speed	125 mph
0 - 60 mph	9.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	331 Nm at 1.800 rpm
Engine capacity	1.988 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-10-18
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2021-12-15
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	29
Total items failed	14

## MOT #18 2020-12-10 12:36

MOT test number 400218599626

Result ✓ Passed

Next expiry date 2021-12-15

- Advice** Advice on slight hand brake travel and look at n/s/r hand brake
- Advice** Advice on heavy surface corrosion at rear floor and inner sills and floor at rear
- Advice** Advice on further look at front brakes sticking slight and o/s/r
- Advice** Advice on heavy surface corrosion at front and rear axles and suspension
- Advice** Advice on slight exhaust blow and slight hole at exhaust down pipe flex y

## MOT #17 2020-12-10 12:36

MOT test number 543153311415

Result ✗ Failed

- Advice** Advice on slight exhaust blow and slight hole at exhaust down pipe flex y
- Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Advice** Advice on slight hand brake travel and look at n/s/r hand brake
- Advice** Advice on heavy surface corrosion at rear floor and inner sills and floor at rear
- Advice** Advice on further look at front brakes sticking slight and o/s/r
- Advice** Advice on heavy surface corrosion at front and rear axles and suspension

**MOT #16** 2019-12-16 13:17**MOT test number** 809373876719**Result** ✓ Passed

**Advice** Nearside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement  
RADIUS ARM (5.3.4 (a) (i))

**MOT #15** 2019-12-03 15:15**MOT test number** 468974991052**Result** ✗ Failed

**MAJOR** Offside Rear Parking brake inoperative on one side (1.4.1 (a))

**Advice** Central Upper Fuel Pipe/s corroded O/S

**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MAJOR** Offside Rear Brake cable insecure (1.1.15 (c))

**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MAJOR** Offside Rear Upper Fuel pipe leaking (6.1.3 (b) (i))

**Minor** Offside Rear Upper Brake pipe inadequately clipped or supported (1.1.11 (d) (i))

**MAJOR** Nearside Rear Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MAJOR** Offside Rear Upper Suspension component mounting prescribed area excessively corroded significantly reducing structural strength SILL AREA (5.3.6 (a) (i))

**MOT #14** 2018-11-20 14:52**MOT test number** 330702285024**Result** ✓ Passed**MOT #13** 2017-12-08 16:44**MOT test number** 185121800712**Result** ✓ Passed

**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)

**Advice** Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**MOT #12**

2017-11-30 12:17

**MOT test number**

349093190796

**Result**

✗ Failed

- Fail** Brake pipe excessively corroded front to rear (3.6.B.2c)
- Fail** Offside Rear Seat belt anchorage prescribed area is excessively corroded sill (5.2.6)
- Fail** Nearside Front Lower Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)
- Fail** Headlamp not working on dipped beam (1.7.5a)
- Fail** Nearside Rear wheel bearing has excessive play (2.6.2)
- Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)
- Fail** Nearside Rear Seat belt anchorage prescribed area is excessively corroded sill (5.2.6)
- Fail** Nearside Rear Tyre has ply or cords exposed side wall split (4.1.D.1b)
- Advice** Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Fail** Nearside Rear Direction indicators incorrect colour (1.4.A.2f)

**MOT #11**

2016-11-10 12:04

**MOT test number**

496887987695

**Result**

✓ Passed

- Advice** Both front to rear brake pipes under-sealed at time of test

**MOT #10**

2015-11-26 15:18

**MOT test number**

881623001719

**Result**

✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2014-12-03 13:35**MOT test number** 449547234398**Result** ✓ Passed**MOT #8** 2013-10-28 08:36**MOT test number** 335471203329**Result** ✓ Passed**MOT #7** 2013-10-25 13:46**MOT test number** 375078993478**Result** ✗ Failed**Fail** Offside Front Wheel nut(s) missing (4.2.A.1e)**Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)**MOT #6** 2012-11-16 16:46**MOT test number** 298141822391**Result** ✓ Passed**MOT #5** 2012-11-16 12:35**MOT test number** 927201022371**Result** ✗ Failed**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #4** 2011-12-16 15:43**MOT test number** 485030151397**Result** ✓ Passed



MOT #3	2010-10-20 16:26
MOT test number	991543190254
Result	✓ Passed

MOT #2	2009-08-25 10:18
MOT test number	424237739296
Result	✓ Passed
<div>Advice</div> Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

MOT #1	2009-06-09 10:21
MOT test number	220790669474
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
1 December 2021

X

MOT

Expired:  
15 December 2021

Tax status	Expired at 1 December 2021
Days left	881 days too late
MOT expiry date	15 December 2021
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-05-31
Last registration	2020-12-10
Complete history	<a href="#">See info</a>



Registration #1	2006-05-31	14 mi
Registration #2	2009-06-09	41.363 mi
Registration #3	2009-08-25	41.843 mi
Registration #4	2010-10-20	47.079 mi
Registration #5	2011-12-16	52.833 mi
Registration #6	2012-11-16	57.879 mi
Registration #7	2012-11-16	57.879 mi
Registration #8	2013-10-25	61.982 mi
Registration #9	2013-10-28	61.982 mi
Registration #10	2014-12-03	68.134 mi
Registration #11	2015-05-20	75.277 mi
Registration #12	2015-05-20	75.277 mi
Registration #13	2015-05-20	75.277 mi
Registration #14	2015-05-20	75.277 mi
Registration #15	2015-05-20	75.277 mi
Registration #16	2015-05-20	75.277 mi
Registration #17	2015-05-20	75.277 mi
Registration #18	2015-05-20	75.277 mi
Registration #19	2015-05-20	75.277 mi
Registration #20	2015-05-20	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1502 kg
Max. allowed weight	2015 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	0601121441376G