



report date: 2024-03-28

General information

Make	CITROEN
Model	C-CROSSER CODE
Colour	Black
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	156 BHP
Max. torque	380 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	47.9 mpg
Consumption combined	39.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

MOT #8	2017-01-30 17:20
MOT test number	425944110387
Result	✓ Passed
Next expiry date	2018-01-29

MOT #7	2017-01-16 15:32
MOT test number	958056051421
Result	✗ Failed

Fail Offside Stop lamp not working (1.2.1b)

MOT #6	2014-09-17 11:18
MOT test number	106960064297

Result	✓ Passed
---------------	----------

- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Items removed from driver's view prior to test
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)



MOT #5

2014-09-16 13:13

MOT test number

329529654405

Result		✗ Failed
Fail	Nearside Registration plate lamp not working (1.1.C.1d)	
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)	
Notice	Child seat fitted not allowing full inspection of adult belt	
Advice	Nearside Brake pipe slightly corroded (3.6.B.2c)	
Notice	Engine covers fitted obscuring some components in the engine bay	
Advice	Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)	
Fail	Offside Brake pipe excessively corroded (3.6.B.2c)	
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Notice	Under-trays fitted obscuring some underside components	
Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)	

**MOT #4** 2013-06-11 14:07**MOT test number** 298942663423**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Notice** Nail in offside rear tyre**Advice** Parking brake lever has little reserve travel (3.1.6b)**Notice** Rear tyres perishing**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Play in steering rack inner joint(s)**Advice** Offside Inner Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2012-07-11 16:41**MOT test number** 948073792115**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Exhaust noisy (7.1.4)**Notice** Nail in rear tyre**MOT #2** 2011-07-06 15:55**MOT test number** 967917981122**Result** ✓ Passed



MOT #12011-07-04 15:58

MOT test number269445681142

ResultX Failed

- Fail

Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail

Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
- Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2008-04-30
Last registration	2017-01-30
Complete history	See info



Registration #1	2008-04-30	21 mi
Registration #2	2011-07-04	43.666 mi
Registration #3	2011-07-06	43.666 mi
Registration #4	2012-07-11	60.353 mi
Registration #5	2013-06-11	75.775 mi
Registration #6	2015-05-20	95.277 mi
Registration #7	2015-05-20	95.277 mi
Registration #8	2015-05-20	95.277 mi
Registration #9	2015-05-20	95.277 mi
Registration #10	2015-05-20	95.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1805 mm
Height	1715 mm
Length	4645 mm
Wheel base	2670 mm
Kerb weight	1750 kg
Max. allowed weight	2410 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	DZ554007100