



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	COUPE SIII
Colour	Grey
Year of manufacture	2008
Top speed	129 mph
0 - 60 mph	9.3 seconds
Gearbox	4 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	186 Nm at 4.500 rpm
Engine capacity	1.975 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.3 mpg
CO2 emission	193 g/km
CO2 label	J






Internet history

Entry 1

Date	2021-09-19
Pictures	20
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-24
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	22
Total items failed	6

MOT #16	2023-10-25 13:22
MOT test number	764890530905
Result	✓ Passed
Next expiry date	2024-10-24
Advice	Offside Rear Tyre worn close to legal limit/worn on edge and stepping on tread (5.2.3 (e))
Advice	Coil spring corroded All 4 (5.3.1 (b) (i))
Advice	Front Tyre worn close to legal limit/worn on edge n/s and o/s inner and outer edges (5.2.3 (e))
Advice	Rear Brake pipe corroded, covered in grease or other material n/s and o/s (1.1.11 (c))
Advice	Front Tyre slightly damaged/cracking or perishing inner and outer side walls but not to cords (5.2.3 (d) (ii))

**MOT #15** 2023-10-24 11:19**MOT test number** 627930076781**Result** ✗ Failed**Fail** Offside Rear Registration plate lamp missing in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge and stepping on tread (5.2.3 (e))**Advice** Rear Brake pipe corroded, covered in grease or other material n/s and o/s (1.1.11 (c))**Fail** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Front Tyre worn close to legal limit/worn on edge n/s and o/s inner and outer edges (5.2.3 (e))**Fail** Offside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Front Tyre slightly damaged/cracking or perishing inner and outer side walls but not to cords (5.2.3 (d) (ii))**Advice** Coil spring corroded All 4 (5.3.1 (b) (i))**MOT #14** 2022-10-03 14:43**MOT test number** 697037701051**Result** ✓ Passed**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))**MOT #13** 2021-09-11 09:16**MOT test number** 822336571124**Result** ✓ Passed**MOT #12** 2020-09-30 11:13**MOT test number** 272479937257**Result** ✓ Passed**MOT #11** 2019-09-13 14:43**MOT test number** 250801055521**Result** ✓ Passed

**MOT #10** 2018-09-22 10:32**MOT test number** 400633920335**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))**MOT #9** 2017-09-27 12:24**MOT test number** 325967073668**Result** ✓ Passed**MOT #8** 2017-09-27 10:34**MOT test number** 338429765683**Result** ✗ Failed**Fail** Nearside Steering rack gaiter split (2.2.D.2d)**MOT #7** 2016-10-01 10:22**MOT test number** 859445735264**Result** ✓ Passed**MOT #6** 2015-09-26 13:25**MOT test number** 339296702331**Result** ✓ Passed**MOT #5** 2015-09-25 15:04**MOT test number** 455117371468**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Steering rack gaiter split (2.2.D.2d)

**MOT #4** 2014-09-26 14:34**MOT test number** 229439964233**Result** ✓ Passed**Advice** Offside Front Steering rack gaiter deteriorated (2.2.D.2d)**MOT #3** 2013-09-27 14:05**MOT test number** 819670373226**Result** ✓ Passed**Advice** Offside Front Steering rack gaiter deteriorated (2.2.D.2d)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-09-21 15:41**MOT test number** 109955062287**Result** ✓ Passed**Notice** Nail in offside rear tyre**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in nearside rear tyre**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2011-10-04 14:08**MOT test number** 825807971283**Result** ✓ Passed**Notice** Nail in nearside front tyre



Tax & MOT check

✓
Taxed

Tax due:
1 March 2025

✓
MOT

Expires:
24 October 2024

Tax status	Valid until 1 March
Days left	307
MOT expiry date	24 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	MF58YLD
Plate since	2019-03-28
Current registration	MF58YLD
Plate since	2019-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-09-29
Last registration	2023-10-25
Complete history	See info



Registration #1	2008-09-29	7 mi
Registration #2	2011-10-04	16.391 mi
Registration #3	2012-09-21	21.968 mi
Registration #4	2013-09-27	28.750 mi
Registration #5	2014-09-26	35.416 mi
Registration #6	2015-09-25	43.191 mi
Registration #7	2015-09-26	43.193 mi
Registration #8	2016-10-01	50.308 mi
Registration #9	2017-09-27	57.891 mi
Registration #10	2018-09-27	65.377 mi
Registration #11	2019-09-27	72.877 mi
Registration #12	2020-09-27	80.377 mi
Registration #13	2021-09-27	87.877 mi
Registration #14	2022-09-27	95.377 mi
Registration #15	2023-09-27	102.877 mi
Registration #16	2024-09-27	110.377 mi
Registration #17	2025-09-27	117.877 mi
Registration #18	2026-09-27	125.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1312 kg
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4GC7063370