



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	CLK CLK270 CDI AVANTGARDE
Colour	Bronze
Year of manufacture	2004
Top speed	143 mph
0 - 60 mph	9.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	170 BHP
Max. torque	400 Nm at 1.800 rpm
Engine capacity	2.685 cc
Cylinders	5
Fuel type	Diesel
Consumption city	29.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.2 mpg
CO2 emission	183 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-09-12
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-05-17
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	28
Total items failed	20

MOT #22 2023-05-18 16:41

MOT test number 503918523149

Result ✓ Passed

Next expiry date 2024-05-17

**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Manufacturer undercover fitted not allowing full inspection and rear slightly corroded

**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #21 2022-04-06 09:46

MOT test number 748949838424

Result ✓ Passed

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Rear rear subframe rusty

MOT #20 2021-04-07 14:37

MOT test number 469839167830

Result ✓ Passed

**MOT #19**

2021-04-06 15:53

**MOT test number**

362012319320

**Result****✗ Failed****Fail** Offside Headlamp light source and lamp not compatible (4.1.4 (c))**Fail** Nearside Headlamp light source and lamp not compatible (4.1.4 (c))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #18**

2019-10-04 14:06

**MOT test number**

352227393000

**Result****✓ Passed****MOT #17**

2019-10-01 09:21

**MOT test number**

127707644121

**Result****✗ Failed****Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Nearside Front Suspension arm ball joint excessively worn steel suspension arm,second in from front of vehicle (5.3.4 (a) (i))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Offside Front Suspension arm ball joint excessively worn steel suspension arm,second in from front of vehicle (5.3.4 (a) (i))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #16**

2018-10-01 13:04

**MOT test number**

484116943693

**Result**

✓ Passed

**Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement Both Nearside/Offside (5.3.4 (a) (i))

**Advice** Rear Tyre worn close to legal limit/worn on edge Both Nearside/Offside (5.2.3 (e))

**Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement Both Nearside/Offside (5.3.4 (a) (i))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #15**

2018-09-29 09:06

**MOT test number**

442931542642

**Result**

✗ Failed

**Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement Both Nearside/Offside (5.3.4 (a) (i))

**Advice** Rear Tyre worn close to legal limit/worn on edge Both Nearside/Offside (5.2.3 (e))

**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement Both Nearside/Offside (5.3.4 (a) (i))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #14**

2017-09-20 12:56

**MOT test number**

367866422475

**Result**

✓ Passed

**MOT #13**

2016-09-19 12:15

**MOT test number**

509958652087

**Result**

✓ Passed

**MOT #12** 2015-10-07 12:38**MOT test number** 797029524612**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2015-10-07 10:21**MOT test number** 145335253623**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Exhaust emits an excessive level of metered smoke (7.4.B.3a)**MOT #10** 2014-10-06 11:00**MOT test number** 106549374254**Result** ✓ Passed**MOT #9** 2013-09-20 16:14**MOT test number** 259213463285**Result** ✓ Passed**Notice** Headlights slight different shades of white**Notice** Front tyres bald on edges

**MOT #8** 2013-09-18 16:33**MOT test number** 679061263255**Result** ✗ Failed

- Fail** Offside Front Headlamp insecure (1.7.3)
- Fail** Front Headlamp levelling device obviously defective (1.7.2)
- Notice** Headlights slight different shades of white
- Pass with rectification** Offside Front Headlamp aim too low (1.8)
- Fail** Front Headlamp cleaning device inoperative (1.7.2)
- Notice** Front tyres bald on edges

**MOT #7** 2012-10-01 09:29**MOT test number** 948185172274**Result** ✓ Passed**MOT #6** 2011-10-07 12:23**MOT test number** 459500881215**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2010-09-28 14:22**MOT test number** 200561570211**Result** ✓ Passed

**MOT #4** 2009-09-28 13:55**MOT test number** 102571579276**Result** ✓ Passed**Advice** Rear Stop lamp deteriorated, but still visible from a reasonable distance (1.2.1d)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2008-10-03 10:43**MOT test number** 293857378277**Result** ✓ Passed**MOT #2** 2007-10-08 16:12**MOT test number** 311161287488**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2007-10-08 11:35**MOT test number** 120381587212**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
17 May 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	17 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-28
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2004-07-26
Last registration	2023-05-18
Complete history	<a href="#">See info</a>



Registration #1	2004-07-26	25 mi
Registration #2	2007-10-08	38.139 mi
Registration #3	2007-10-08	38.139 mi
Registration #4	2008-10-03	45.326 mi
Registration #5	2009-09-28	55.070 mi
Registration #6	2010-09-28	59.296 mi
Registration #7	2011-10-07	63.952 mi
Registration #8	2012-10-01	67.195 mi
Registration #9	2013-09-18	70.478 mi
Registration #10	2013-09-20	70.478 mi
Registration #11	2014-10-06	79.057 mi
Registration #12	2015-10-07	87.249 mi
Registration #13	2016-09-20	95.441 mi
Registration #14	2017-09-20	103.633 mi
Registration #15	2018-09-20	111.825 mi
Registration #16	2019-09-20	120.017 mi
Registration #17	2020-09-20	128.209 mi
Registration #18	2021-09-20	136.401 mi
Registration #19	2022-09-20	144.593 mi
Registration #20	2023-05-18	152.785 mi
Registration #21	2023-05-18	152.785 mi
Registration #22	2023-05-18	152.785 mi
Registration #23	2023-05-18	152.785 mi
Registration #24	2023-05-18	152.785 mi

More info >



Dimensions & weight

Width	1740 mm
Height	1413 mm
Length	4638 mm
Wheel base	2715 mm
Kerb weight	1645 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	2
Number of axles	2
Engine number	61296730287156