



Mercedes-Benz



report date: 2024-03-28

General information

|                     |                         |
|---------------------|-------------------------|
| Make                | MERCEDES                |
| Model               | A-CLASS A150 CLASSIC SE |
| Colour              | Silver                  |
| Year of manufacture | 2008                    |
| Top speed           | 106 mph                 |
| 0 - 60 mph          | 13.5 seconds            |
| Gearbox             | 1 speed CVT             |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 95 BHP              |
| Max. torque             | 140 Nm at 3.500 rpm |
| Engine capacity         | 1.498 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 33.2 mpg            |
| Consumption extra urban | 51.4 mpg            |
| Consumption combined    | 42.8 mpg            |
| CO2 emission            | 157 g/km            |
| CO2 label               | G                   |





## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2021-01-19 |
| MOT pass rate      | 69 %       |
| MOT passed         | 9          |
| Failed MOT tests   | 4          |
| Total advice items | 32         |
| Total items failed | 8          |

MOT #13 2019-07-20 12:48

MOT test number 953824623523

Result ✓ Passed

Next expiry date 2021-01-19

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Rear Stop lamp(s) light intensity obviously reduced (4.3.3 (a) (i))

MOT #12 2019-07-20 12:48

MOT test number 588633266061

Result ✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Rear Stop lamp(s) light intensity obviously reduced (4.3.3 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #11** 2018-01-04 15:19**MOT test number** 561566232714**Result** ✓ Passed**Advice** Offside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Oil leak**MOT #10** 2017-01-06 14:54**MOT test number** 490665671956**Result** ✓ Passed**Advice** Engine mil lamp on**Advice** Temp light came on during emmissions test**MOT #9** 2017-01-06 09:09**MOT test number** 896580361387**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Front Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Temp light came on during emmissions test**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Engine mil lamp on**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside front brake disc ground to pad**MOT #8** 2016-01-11 09:38**MOT test number** 546469306258**Result** ✓ Passed

**MOT #7**

2015-01-12 16:29

**MOT test number**

148702315007

**Result**

✓ Passed

- Notice** Engine Management light is on
- Notice** Brake Pedal Anti-Slip Rubber is damaged
- Notice** Nail in offside rear tyre
- Notice** Offside front tyre is worn on the edges
- Notice** Oil leak
- Notice** Nail in nearside rear tyre

**MOT #6**

2015-01-12 11:03

**MOT test number**

167942615025

**Result**

✗ Failed

- Notice** Nail in nearside rear tyre
- Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
- Notice** Engine Management light is on
- Notice** Brake Pedal Anti-Slip Rubber is damaged
- Notice** Nail in offside rear tyre
- Notice** Offside front tyre is worn on the edges
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Oil leak

**MOT #5**

2014-01-23 11:14

**MOT test number**

166983624430

**Result**

✓ Passed

**MOT #4** 2013-01-03 14:36**MOT test number** 148723203060**Result** ✓ Passed**Notice** Nearside rear tyre deteriorated and damaged**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Offside steering arm has play**MOT #3** 2011-12-29 15:00**MOT test number** 488483761388**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2** 2011-12-29 10:12**MOT test number** 929223861336**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #1** 2010-12-21 11:35**MOT test number** 402955850444**Result** ✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
28 August 2020

✕  
MOT

Expired:  
19 January 2021

|                  |                                 |
|------------------|---------------------------------|
| Tax status       | Expired at 28 August 2020       |
| Days left        | 1340 days too late              |
| MOT expiry date  | 19 January 2021                 |
| Full MOT history | <a href="#">See MOT history</a> |

Tax calculation

|   |            |
|---|------------|
| Vehicle class                           | 48         |
| Band                                    | G          |
| Single payment (12 months)              | £ 240,00,- |
| Single six month payment                | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >





Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

|                      |  |
|----------------------|--|
| Number of plates     | 1  |
| Current registration |  <b>KR57GWV</b> |
| Plate since          | 2019-06-29   |
| Current registration |  <b>KR57GWV</b> |
| Plate since          | 2019-06-29   |

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

|                   |          |          |
|-------------------|----------|----------|
| Finance company   | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type    | REDACTED | REDACTED |
| Agreement term    | REDACTED | REDACTED |
| Agreement number  | REDACTED | REDACTED |
| Contact info      | REDACTED | REDACTED |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 14                       |
| First mileage registration | 2008-01-03               |
| Last registration          | 2019-07-20               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2008-01-03 | 20 mi     |
| Registration #2  | 2010-12-21 | 4.923 mi  |
| Registration #3  | 2011-12-29 | 24.812 mi |
| Registration #4  | 2011-12-29 | 24.812 mi |
| Registration #5  | 2013-01-03 | 32.659 mi |
| Registration #6  | 2014-01-23 | 40.212 mi |
| Registration #7  | 2015-01-12 | 47.079 mi |
| Registration #8  | 2015-01-20 | 55.277 mi |
| Registration #9  | 2015-01-20 | 55.277 mi |
| Registration #10 | 2015-01-20 | 55.277 mi |
| Registration #11 | 2015-01-20 | 55.277 mi |
| Registration #12 | 2015-01-20 | 55.277 mi |
| Registration #13 | 2015-01-20 | 55.277 mi |
| Registration #14 | 2019-07-20 | 55.277 mi |

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

|             |         |
|-------------|---------|
| Width       | 1764 mm |
| Height      | 1593 mm |
| Length      | 3883 mm |
| Wheel base  | 2568 mm |
| Kerb weight | 1225 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 54 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 5                     |
| Number of seats    | 5                     |
| Engine number      | 26692030527015        |